

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI24090414/KNP3E2**Date:** 16/01/2025REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC04317
<b>Claimant Vehicle No :</b>	SLB3833R	<b>Insured Vehicle No :</b>	YN4186B
Date of Loss:	18/09/2024	Nature of Claim:	TP
		Claim No:	M2405507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLB3833R</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Standard (AUTO) (2WD) (A)	Engine No:	1ZR0G87430
Reg. Date:	18/05/2021 (Man. Year: 2021)	Chassis No:	MR2BE3BE600014756
Colour:	Metallic Red	Odometer:	59566 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,874.75	2,644.84	1,229.91	31.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	840.00	530.00	38.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,244.75</b>	<b>3,484.84</b>	<b>1,759.91</b>	<b>33.56</b>
<b>+ GST 9.00/9.00% (S\$)</b>	<b>472.03</b>	<b>313.64</b>	<b>158.39</b>	<b>33.56</b>
<b>Nett Amount (S\$)</b>	<b>5,716.78</b>	<b>3,798.48</b>	<b>1,918.30</b>	<b>33.56</b>

INSPECTION

Date of Assignment:	24/09/2024	
Date Inspected:	27/09/2024	Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 16 Jan 2025)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 Standard (AUTO)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLB3833R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT HOOD	Bent	870.00 FL	*870.00 FL
2	1		*FRT HOOD INSULATOR	Serviceable	260.00 FL	*- FL
3	1		*FRT HOOD LOCK	Repair	140.00 FL	*- FL
4	1		*FRT HOOD RUBBER	Serviceable	128.00 FL	*- FL
5	1		*FRT BUMPER LH CHROME	Serviceable	90.00 FL	*- FL
6	1		*WIPER GARNISH	Dented / Cut	770.00 FL	*727.12 FL
7	1		*LH HEADLAMP	Serviceable	900.00 FL	*- FL
8	1		*FRT WINDSCREEN	Cut	1,250.00 FL	*1,250.00 FL
9	1		*SETS FRT WINDSCREEN MOULDING	Necessary	160.00 FL	*126.00 FL
10	1		*FRT RADIATOR GRILLE (LOWER)	Dented	500.00 FL	*500.00 FL
11	1		*FRT TOW COVER	Serviceable	45.00 FL	*- FL
12	1		*SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,153.00</b>	<b>3,513.12</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,278.25	868.28
<b>Total Parts (S\$)</b>	<b>3,874.75</b>	<b>2,644.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK PUTTY REMOVE REFIT REALIGN AFFECTED PARTS	New	600.00	300.00
2	TO PUTTY AND RESPRAY AFFECTED PARTS	New	600.00	400.00
3	HL WIRING	New	50.00	20.00
4	TO REMOVE / REFIT FRT WINDSCREEN	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,370.00</b>	<b>840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >