



CompartDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SLB3833R

Make & Model : TOYOTA ALTIS

Year of Manufacture : 2021

Chassis No. : _____

Engine No. : _____

Policy No. : _____

Time of Accident : _____

Ins Company : _____

Excess : _____

Date of Accident : 18.09.24

Suggested Days of Repair : 4

In-house Vehicle Assessor

Case Owner : HAKIM

Signature : 98328740

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,158.00

Plus/Less 25% \$ 789.50

Total of Cost / List \$ 2,368.50

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items _____

Total Parts Cost (Appendix A) \$ 2,368.50

Labour (Appendix B) \$ 1,250.00

Total Repair Cost \$ 3,618.50

Contact No
Operation
KELVIN SU
TEL: 9786 4236
E: kelvinsukwen@cdge.com.sg

JOHARI
TEL: 972103705
E: joharibh@sparkcarcare.com

SUN PIN
TEL: 9728 8916
E: oisunpin@cdge.com.sg

*Not Authorized
Repair By pain
@ 348484*

The above total will be subjected to 8% G.S.T.

Name of Surveyor : Keneth

Company : LKk

Survey conducted on : 27/9/24 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 27/9/24

Spark Car Care

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SLB3233R Case Owner : HAKIM
 Make & Model : TOYOTA ALTIS Year Manufacture : 2021
 Chassis No : MR2BE3BE600014756 Engine No : _____
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRT HOOD			\$ <i>By</i> 870.00			✓
2	FRT HOOD INSULATOR		<i>Sn</i>	\$ 260.00			X
3	FRT HOOD LOCK			\$ <i>R</i> 140.00			X
4	FRT HOOD RUBBER			\$ <i>Sn</i> 128.00			X
5	FRT BUMPER LH CHROME			\$ <i>SoC</i> 90.00			X
6	WIPER GARNISH <i>727.12</i>			<i>Adlwr</i> 770.00			✓
7	LH HEADLAMP			\$ <i>Sn</i> 900.00			X
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Spark Car Care

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. : SLB3833R
 Make & Model : TOYOTA ALTIS

Case Owner : HAKIM
 Year of Manufacture : _____

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO KNOCK PUTTY REMOVE REFIT REALIGN AFFECTED PARTS	\$600.00	<u>300</u>
2	TO PUTTY AND RESPRAY AFFECTED PARTS	\$600.00	<u>400</u>
3	HL WIRING	\$50.00	<u>20</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

