

ASS. REC. BY:

REF:

09/C72 240904171Kqk3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm, or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

2/10 11 Pm @ 3900. Car in area @ 1824209, 82%

Date/Time, File Pass to?



: Prell. Report

03/10 11:15 AM



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Eclaining - TP

3900



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 23/09/24
 VEHICLE : SND6525B
 MAKE/MODEL : TOYOTA / NOAH
 CHASSIS NO : ZWR80-0506389
 MILLAGE :
 TYRE SIZE : 195/65R15
 DOA : 20/09/24

Not Notified
 1/1 Rmp & 3900h
 Recovery After Rain
 4 days

LIST ITEM

01 PC	REAR RH FENDER	R	\$	2,041.77	X
01 PC	REAR RH FENDER INNER SHEILD	Per	\$	368.50	X
01 PC	REAR RH MUDFLAT	Per	\$	256.30	X
01 PC	REAR RH FENDER INNER TRIM BOARD	mfg cm	\$	848.91	X
01 PC	REAR AIR COND BLOWER BOX ASSY	Per	\$	2,565.45	X
01 PC	REAR RH DOOR 1616.70	R	\$	1,990.56	X
01 PC	REAR RH DOOR WEATERSTRIP	\$ Per		395.20	X
01 PC	REAR RH DOOR INNER TRIM BOARD	Per	\$	2,147.88	X
01 PC	REAR RH DOOR STEP GANISH 312.60	cm	\$	442.74	X
01 PC	REAR RH DOOR POWER MOTOR ASSY	Per	\$	3,562.10	X
01 PC	REAR RH ROCKER PANEL Parnish P-1	cm	\$	720.48	X
01 PC	REAR RH WHEEL BEARING	R	\$	380.60	X
01 PC	REAR RH ABSORBER	Per	\$	521.60	X
			\$	16,242.09	

251

Special Nett

10 PC	INNER TRIM BOARD CLIP @ \$8.00	R	\$	80.00	X
01 PC	REAR RH RIM	\$		1,200.00	X
01 PC	REAR RH TYRES	\$		250.00	X
01 PC	GLASS SEALANT	\$		100.00	X
		\$		1,630.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	2,000.00	4501
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA	\$	900.00	8001
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	201
4. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	250.00	301
5. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING	\$	50.00	X
6. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGMENT	\$	150.00	601
7. TO SUPPLY LABOUR TO DISMANTLE FENDER INNER UPHOLSTER	\$	300.00	X
8. TO SUPPLY LABOUR TO REFILL AIR COND GAS	\$	120.00	X
9. TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR FENDER GLASS	\$	300.00	X
	\$	4,270.00	

TOTAL PARTS

TOTAL SPECIAL NETT

TOTAL LABOUR

TOTAL COST OF REPAIR

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 16,242.09
 \$ 1,630.00
 \$ 4,270.00
 \$ 22,142.09