

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24060178/RNP3E2  
**Date:** 29/08/2024REFERENCE

Insured/Claimant:	LEE JUN WEI, ERIC	Policy No:	2070161277		
Date of Loss:	20/06/2024	Nature of Claim:	OD	Claim No:	8618323061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMX3836E</b>	Engine No:	DLH067039
Make & Model:	AUDI A7 SPORTBACK, 2.0 TFSI (A)	Chassis No:	WAUZZZF21LN013368
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	137914 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$229,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R20	Rear Tyre Size:	255/40 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,858.00	16,553.76	9,304.24	35.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,712.00	6,332.00	4,380.00	40.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>36,570.00</b>	<b>22,885.76</b>	<b>13,684.24</b>	<b>37.42</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	35,970.00	22,285.76	13,684.24	38.04
<b>+ GST 9.00/9.00% (S\$)</b>	3,237.30	2,005.72	1,231.58	38.04
<b>Nett Amount (S\$)</b>	<b>39,207.30</b>	<b>24,291.48</b>	<b>14,915.82</b>	<b>38.04</b>

INSPECTION

Date of Assignment:	21/06/2024		
Date Inspected:	24/06/2024	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days		

**Adjuster:** MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Bent	2,163.00 FS	*1,730.40 FS
2	1		*FRONT FENDER BRACE - LH	Not Necessary	193.00 FS	*- FS
3	1		*FRONT FENDER BRACKET - LH UPPER	Not Necessary	55.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	72.00 FS	*- FS
5	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	94.00 FS	*- FS
6	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	332.00 FS	*- FS
7	1		*FRONT WHEEL SPOILER - LH	Not Necessary	207.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - LH	Not Necessary	82.00 FS	*- FS
9	1		*FRONT FENDER LOWER BRACKET - LH	Not Necessary	34.00 FS	*- FS
10	1		*FRONT FENDER LOWER BRACKET SUPPORT - LH	Not Necessary	8.00 FS	*- FS
11	1		*SIDE MEMBER ATTACHMENT PARTS - LH	Not Necessary	153.00 FS	*- FS
12	1		*SIDE MEMBER ADHESIVE TAPES - LH	Not Necessary	69.00 FS	*- FS
13	1		*FRONT DOOR - LH	Bent	5,395.00 FS	*4,316.00 FS
14	1		*FRONT DOOR CATCH - LH	Not Necessary	160.00 FS	*- FS
15	1		*FRONT DOOR SEAL, OUTER - LH	Necessary	275.00 FS	*220.00 FS
16	1		*FRONT DOOR RETAINING STRIP OUTER SEAL - LH	Necessary	9.00 FS	*6.72 FS
17	2		*FRONT DOOR HINGE - LH UPPER / LOWER	Not Necessary	264.00 FS	*- FS
18	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	390.00 FS	*- FS
19	1		*FRONT DOOR CORNER TRIM - LH	Not Necessary	97.00 FS	*- FS
20	1		*FRONT DOOR SEALING ELEMENT - LH	Not Necessary	22.00 FS	*- FS
21	1		*FRONT DOOR SEALING ELEMENT - LH	Not Necessary	22.00 FS	*- FS
22	1		*FRONT DOOR WINDOW APERTURE SEAL - LH INNER	Not Necessary	570.00 FS	*- FS
23	1		*FRONT WINDOW SLOT SEAL - LH OUTER	Not Necessary	398.00 FS	*- FS
24	1		*FRONT DOOR WINDOW - LH	Scratched	439.00 FS	*350.80 FS
25	1		*FRONT WING MIRROR GLASS - LH	Missing	1,437.00 FS	*1,149.60 FS
26	1		*FRONT WING MIRROR CAP - LH	Cracked	392.00 FS	*313.20 FS
27	1		*FRONT WING MIRROR MOUNT - LH	Broken	3,385.00 FS	*2,708.00 FS
28	1		*FRONT DOOR HANDLE - LH	Scratched	521.00 FS	*416.40 FS
29	1		*FRONT DOOR HANDLE CAP - LH	Scratched	116.00 FS	*92.80 FS
30	2		*FRONT DOOR HANDLE UNDERLAY - LH INNER / OUTER	Not Necessary	15.00 FS	*- FS
31	1		*FRONT DOOR MOUNTING BAR	Not Necessary	203.00 FS	*- FS
32	1		*REAR DOOR - LH	Bent	5,395.00 FS	*4,316.00 FS
33	1		*REAR DOOR CATCH - LH	Not Necessary	160.00 FS	*- FS
34	1		*REAR DOOR SEAL, OUTER - LH	Necessary	275.00 FS	*220.00 FS
35	1		*REAR DOOR RETAINING STRIP - LH	Necessary	6.00 FS	*4.64 FS
36	1		*STONE CHIP FILM FOR SIDE MEMBER	Not Necessary	249.00 FS	*- FS
37	1		*REAR DOOR HINGER - LH UPPER / LOWER	Not Necessary	131.00 FS	*- FS
38	1		*REAR DOOR HINGER - LH LOWER	Not Necessary	193.00 FS	*- FS
39	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	390.00 FS	*- FS
40	1		*CHROME ROOF MOLDING - LH	Deformed	887.00 FS	*709.20 FS
41	1		*FRONT TYRE - LH (NPA)	Not Necessary	0.00 FS	*- FS
42	1		*REAR TYRE - LH (NPA)	Not Necessary	0.00 FS	*- FS
43	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 25,858.00 16,553.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND REINSTALL FRONT BUMPER AND LHS SILL PANEL TRIM. TO DISMANTLE AND RENEW LHS FRONT FENDER AND LHS FRONT AND REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	2,250.00
3	TO RESPRAY LHS FRONT AND REAR DOOR, LHS FRONT FENDER, LHS FRONT AND REAR DOOR HANDLES AND LHS WING MIRROR	New	3,800.00	2,350.00
4	TO RENEW LHS FRONT AND REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	560.00	240.00
5	TO SUPPLY AND REINSTALL PAINT PROTECTION FILM ON FENDER AND WING MIRROR COVER (NPA)	New	0.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
7	TO REMOVE AND TRANSFER LHS FRONT REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	800.00
8	PAINT COATING	New	380.00	0.00
9	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS (Supplementary)	New	400.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,712.00</b>	<b>6,332.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >