

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CS/AIG24090418/RVP3E2**Date:** 07/01/2025REFERENCE

Insured/Claimant: CHRISTOPHER CHONG CHI CHUIN (CHRISTOPHER ZHONG QIJUN)

Policy No: 2100471730

Date of Loss: 23/09/2024

Nature of Claim: OD Claim No: 2036917968SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLC7709K**

Make & Model: AUDI Q7, 2.0 TFSI QU (A)

Engine No: CYR015333

Reg. Date: 22/06/2016 (Man. Year: 2016)

Chassis No: WAUZZZ4M1GD064854

Colour: Grey

Odometer: 110535 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$85,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 275/45 R20 Rear Tyre Size: 275/45 R20
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,869.00	8,697.76	23,171.24	72.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,562.00	6,112.00	5,450.00	47.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,431.00	14,809.76	28,621.24	65.90
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	40,431.00	11,809.76	28,621.24	70.79
+ GST 9.00/9.00% (S\$)	3,638.79	1,062.88	2,575.91	70.79
Nett Amount (S\$)	44,069.79	12,872.64	31,197.15	70.79

INSPECTION

Date of Assignment: 25/09/2024

Date Inspected: 25/09/2024 Inspected At:

24 Benoi Sector
Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Torn	3,254.00 FS	*2,603.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	503.00 FS	*- FS
3	1	*FRONT BUMPER AIR GUIDE	Cracked	84.00 FS	*66.96 FS
4	1	*FRONT BUMPER CLOSING - UPPER CENTRE	Serviceable	347.00 FS	*- FS
5	1	*FRONT BUMPER GRILLE	Serviceable	258.00 FS	*- FS
6	1	*FRONT BUMPER CLOSING ELEMENT	Cracked	263.00 FS	*210.40 FS
7	1	*FRONT BUMPER SPOILER - LH / RH	N/S Missing/O/S Not Necessary	526.00 FS	*210.40 FS
8	1	*RADIATOR GRILLE	Serviceable	3,039.00 FS	*- FS
9	1	*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	374.00 FS	*298.80 FS
10	1	*FRONT PARKING AID SENSOR	Missing	286.00 FS	*228.80 FS
11	4	*FRONT PARKING AID SENSOR SEAL RING	Necessary	11.00 FS	*8.64 FS
12	1	*SET FRONT BUMPER WIRING	Not Necessary	751.00 FS	*- FS
13	1	*LED HEADLIGHT - LH	Serviceable	11,979.00 FS	*- FS
14	1	*LIFT CYLINDER - LH	Cracked	238.00 FS	*190.40 FS
15	1	*LIFT CYLINDER HOSE - LH	Cracked	124.00 FS	*99.20 FS
16	1	*FRONT FENDER - LH	Repair	2,043.00 FS	*- FS
17	1	*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	138.00 FS	*- FS
18	1	*FRONT FENDER BRACKET - LH	Not Necessary	76.00 FS	*- FS
19	1	*FRONT FENDER BRACKET - LH	Not Necessary	80.00 FS	*- FS
20	1	*FRONT FENDER BRACE - LH	Not Necessary	210.00 FS	*- FS
21	1	*FRONT WHEEL HOUSING LINER - LH	Torn	289.00 FS	*231.20 FS
22	1	*FRONT WHEEL HOUSING LINER ATTACHMENT - LH	Not Necessary	206.00 FS	*- FS
23	1	*FRONT WHEEL SPOILER - LH OUTER	Cracked	55.00 FS	*43.92 FS
24	1	*FRONT WHEEL SPOILER - LH INNER	Cracked	72.00 FS	*57.36 FS
25	2	*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,548.00 FS	*1,237.60 FS
26	1	*ADDITIONAL RADIATOR	Bent	1,076.00 FS	*860.80 FS
27	1	*ADDITIONAL RADIATOR BRACKET	Necessary	170.00 FS	*136.00 FS
28	1	*ADDITIONAL RADIATOR AIR GUIDE	Cracked	62.00 FS	*49.36 FS
29	1	*RADIATOR COOLANT (6PCS)	Necessary	332.00 FS	*265.44 FS
30	1	*REFRIGENT LINE	Bent	392.00 FS	*314.00 FS
31	1	*REFRIGENT LINE	Bent	281.00 FS	*224.80 FS
32	1	*REFRIGENT LINE	Not Necessary	341.00 FS	*- FS
33	1	*HORN	Not Necessary	270.00 FS	*- FS
34	1	*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
35	1	*FRONT RIM - LHS (NPA)	Cut	0.00 FS	*- FS
36	1	*FRONT TYRE - LHS	Cut	520.00 FS	*520.00 FS
37	1	*SUNDRIES	Necessary	600.00 FS	*31.68 FS
38	1	*FRONT BUMPER UNDERRUN BAR	Cracked	1,011.00 FS	*808.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 31,869.00 8,697.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	450.00	0.00
4	TO REMOVE AND RENEW LHS ADDITIONAL RADIATOR	New	880.00	880.00
5	TO CARRY OUT VACUUM AND REGAS R1234	New	1,200.00	1,200.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	600.00
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,800.00	1,900.00
8	TO RENEW LHS FRONT RIM WITH TYRE AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
9	TO CARRY OUT FRONT CAMERA CALIBRATION AND ADAPTATION	New	480.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
11	TO REMOVE AND RENEW AIRCON REFRIGENT PIPES (Supplementary)	New	480.00	480.00
Gross Labour Cost (\$\$)			11,562.00	6,112.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >