

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090419/UPA3Q2
Date: 11/02/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0003876_03
Claimant Vehicle No : SMW2704P **Insured Vehicle No :** YN118A
 Date of Loss: 20/09/2024 Nature of Claim: TP Claim No: MCV2024D0011086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW2704P**
 Make & Model: MERCEDES-BENZ GLA180, 1.6 URBAN EDITION (A) Engine No: 27091031946684
 Reg. Date: 12/11/2020 (Man. Year: 2019) Chassis No: WDC1569422J688791
 Colour: Grey Odometer: 145189 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,503.00	4,700.90	12,802.10	73.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	1,960.00	5,620.00	74.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,083.00	6,660.90	18,422.10	73.44
+ GST 9.00/9.00% (S\$)	2,257.47	599.48	1,657.99	73.44
Nett Amount (S\$)	27,340.47	7,260.38	20,080.09	73.44
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		7,502.56		

INSPECTION

Date of Assignment: 25/09/2024
 Date Inspected: 25/09/2024 Inspected At: Eurokars Services Pte Ltd (HQ)
 5 UBI CLOSE
 Singapore 408605
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)	
Parts: M1-SUV	MERCEDES-BENZ GLA180 1.6 URBAN EDITION (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMW2704P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Badly Dented	1,070.00 F	*1,070.00 FL
2	1		*FRONT FENDER ARCH GARNISH LH	Distorted	289.00 F	*289.00 FL
3	1		*FRONT FENDER UNDERSHIELD LH	Torn	305.00 F	*305.00 FL
4	10		*FRONT FENDER UNDERSHIELD CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT DOOR LH	Dented / Bent	2,325.00 F	*2,325.00 FL
6	1		*FRONT DOOR HINGE LH UPPER	Not Necessary	265.00 F	*- FL
7	1		*FRONT DOOR HINGE LH LOWER	Not Necessary	175.00 F	*- FL
8	1		*FRONT DOOR CHECKER LH (NPA)	Not Necessary	0.00 F	*- FL
9	1		*SIDE SKIRT LH	Grazed	445.00 F	*445.00 FL
10	1		*FRONT SHOCK ABSORBER LH	Not Necessary	1,068.00 F	*- FL
11	1		*FRONT SHOCK ABSORBER MOUNTING LH	Not Necessary	384.00 F	*- FL
12	1		*FRONT KNUCKLE ARM LH	Not Necessary	1,176.00 F	*- FL
13	1		*FRONT WHEEL BEARING LH	Not Necessary	240.00 F	*- FL
14	1		*FRONT LOWER ARM LH	Not Necessary	840.00 F	*- FL
15	1		*STEERING GEAR	Not Necessary	6,648.00 F	*- FL
16	1		*TIE ROD END LH	Not Necessary	112.00 F	*- FL
17	1		*FRONT RIM LH	Repair	1,344.00 F	*- FL
18	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
19	1		*FRONT FENDER INNER GARNISH LH	Torn	62.00 F	*62.00 FL
20	4		*FRONT FENDER INNER GARNISH CLIPS	Necessary	36.00 F	*36.00 FL
21	6		*SIDE SKIRT LH CLIPS	Necessary	54.00 F	*54.00 FL
22	4		*WINDSCREEN GARNISH BRACKET	Twisted	52.00 F	*52.00 FL
23	6		*SIDE SKIRT BOTTOM CLIPS	Necessary	54.00 F	*54.00 FL
24	1		*FRONT DOOR SEAL LH RUBBER	Necessary	360.00 F	*360.00 FL
25	11		*FRONT DOOR RIVET	Necessary	99.00 F	*99.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,503.00	5,221.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	520.10
Total Parts (S\$)	17,503.00	4,700.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REPLACE FRONT FENDER LH ,FRONT DOOR LH ,SIDE SKIRT LH & ALL ACCIDENT DAMAGED BODYPARTS .TO REPAIR A-PILLAR LH & ALL AREAS AFFECTED BY THE ACCIDENT	New	2,400.00	700.00
2	TO RESPRAY FRONT FENDER LH FRONT DOOR LH	New	2,000.00	600.00
3	TO CARRY OUT BODY CAVITY PRESERVATION	New	250.00	30.00
4	TO REMOVE & REPLACE THE FRONT LH UNDER CARRIAGE INCLUDING STEERING GEAR	New	1,200.00	0.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	0.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	280.00
7	TO TRANSFER THE FRONT DOOR LH MECHANISM	New	300.00	80.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	500.00	150.00
			Gross Labour Cost (\$\$)	7,580.00
				1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >