

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III24090420/ENP3M4**Date:** 02/10/2024**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005589_04
<b>Claimant Vehicle No :</b>	GBD7022X	<b>Insured Vehicle No :</b>	PD1191P
Date of Loss:	20/09/2024	Nature of Claim:	TP
		Claim No:	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBD7022X</b>	Engine No:	1KD2435559
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Chassis No:	KDY2318017302
Reg. Date:	26/03/2015 (Man. Year: 2014)	Odometer:	167136 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Condor 5 mm	Rear Left Side:	Condor 5 mm
Front Right Side:	Condor 5 mm	Rear Right Side:	Condor 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	23/09/2024	
Date Inspected:	23/09/2024	Inspected At: TAN ENG HUAT MOTOR 6 DEFU LANE 10 #01-556 DEFU INDUSTRIAL ESTATE SINGAPORE 539187
Estimated Period of Repair:	0.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Oct 2024)	
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7022X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**