



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBM 9515E

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	AXLE WHEEL FRONT	BENT	\$13.00	\$13.00
1	SET BALANCER HANDLE (RCB)	CUT	\$75.00	\$75.00
1	BASKET SNIPER150	BENT	\$71.00	\$71.00
1	BOX REAR (GIVI) E43N	CUT	\$373.00	\$373.00
1	BRACKET MASTER PUMP RH	BROKEN	\$11.00	\$11.00
1	BRACKET SIDE COVER	BENT	\$13.00	\$13.00
1	BRACKET TANK RESERVOIR	BENT	\$13.00	\$13.00
1	COOLANT (MOBIL) ANTIFREEZE	NECESSARY	\$21.00	\$21.00
1	COVER CRANKCASE 1	CUT	\$155.00	\$155.00
1	COVER FRONT LOWER LH	BROKEN	\$28.00	\$28.00
1	COVER FRONT LOWER RH	BROKEN	\$31.00	\$31.00
1	COVER SET BLACK METALLI X (V1)	BROKEN	\$481.00	\$481.00
1	EMBLEM PANEL FRONT	NECESSARY	\$10.00	\$10.00
1	FOOTREST FRONT LH	BENT	\$23.00	\$23.00
1	FOOTREST REAR LH	CUT	\$21.00	\$21.00
1	FRONT FORK ASSY	BENT	\$505.00	\$505.00
1	FRONT SIGNAL LIGHT ASSY	CUT	\$31.00	\$31.00
1	GASKET CRANKCASE COVER 1	NECESSARY	\$10.00	\$10.00
1	GUIDE AIR 1	BROKEN	\$10.00	\$10.00
1	LEVER BRAKE RH	CUT	\$21.00	\$21.00
1	LEVER CLUTCH	BROKEN	\$25.00	\$25.00
1	LIGHT PILOT FRONT	BROKEN	\$172.00	\$172.00
1	MIRROR LH	CUT	\$31.00	\$31.00
1	MIRROR RH	MISSING	\$31.00	\$31.00
1	OBU TYPE B (12V) NEW	CUT	\$341.00	\$341.00
1	OIL ENGINE (MOBIL) ADVANCE RACING 1 10/40	NECESSARY	\$41.00	\$41.00
1	O-RING	NECESSARY	\$5.00	\$5.00
1	PANEL INNER FRONT HEADLAMP	BROKEN	\$40.00	\$40.00
1	PANEL STAND COVER BIG	CRUSHED	\$40.00	\$40.00
1	PEDAL GEAR ASSY	BENT	\$23.00	\$23.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RADIATOR COMP	BENT	\$171.00	\$171.00
1	RUBBER FOOTREST FRONT	CUT	\$10.00	\$10.00
1	RUBBER PEDAL GEAR	CUT	\$8.00	\$8.00
1	STAY	BENT	\$40.00	\$40.00
1	SET STEERING CONE	NECESSARY	\$54.00	\$54.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$294.80)
			\$2,948.00	\$2,653.20
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	ALIGNMENT BODY	NOT NECESSARY	\$540.00	\$0.00
	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS		\$1,700.00	\$880.00
			\$2,240.00	\$880.00
GRAND TOTAL			\$5,188.00	\$3,533.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,850.00
Report Ref No: CS/FCI24090421/Eqp3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.