



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SME 9289U

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TRUNK LID (SN)	BENT	\$3,258.47	\$3,258.47
1	SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM LH (SN)	NECESSARY	\$350.95	\$350.95
1	SPOILER SATIN BLACK REAR W/SCREEN SIDE TRIM RH (SN)	NECESSARY	\$350.95	\$350.95
1	2K-GLASS GLUE APPLICATION (SN)	NECESSARY	\$166.69	\$166.69
1	ALL PURPOSE CLEANER (SN)	NECESSARY	\$128.05	\$128.05
1	PRIMER (SN)	NECESSARY	\$37.71	\$37.71
1	ACTIVATOR (SN)	NECESSARY	\$32.61	\$32.61
2	APPLICATOR (SN)	NECESSARY	\$27.84	\$27.84
2	RIVETTED CAP NUT (SN)	NECESSARY	\$5.80	\$5.80
1	PACKING ADHESIVE REAR NUMBER PLATE PACKING (SN)	NECESSARY	\$34.00	\$34.00
1	HOOD LATCH BOOT LID LOCK (SN)	SERVICEABLE	\$173.64	\$0.00
1	COVER LOCK SATIN BLACK BOOT LID LOCK COVER (SN)	SCRATCHED	\$17.58	\$17.58
1	VW SIGN BLACK/BRIGHT CHRO (SN)	NECESSARY	\$125.54	\$125.54
1	INSCRIPTION BRIGHT CHROME NAME PLATE - TOURAN (SN)	NECESSARY	\$100.90	\$100.90
1	ADDITIONAL BRAKE LIGHT WI 3RD BRAKELIGHT (SN)	NECESSARY	\$253.99	\$253.99
1	COVER FOR BUMPER PRIMED (SN)	DEFORMED	\$1,307.91	\$1,307.91
1	SPOILER SATIN BLACK (SN)	SCRATCHED	\$396.07	\$396.07
1	BUMPER REINFORCEMENT (SN)	BENT	\$913.16	\$913.16
1	ATTACHMENT STRIP BUMPER CTR BRACKET (SN)	CRACKED	\$84.83	\$84.83
1	GUIDE PIECE LHR BUMPER BRACKET (UPPER) (SN)	SERVICEABLE	\$68.58	\$0.00
1	GUIDE PIECE RHR BUMPER BRACKET (UPPER) (SN)	SERVICEABLE	\$68.58	\$0.00
1	GUIDE PIECE LHR BUMPER BRACKET (SIDE) (SN)	SERVICEABLE	\$66.66	\$0.00
1	GUIDE PIECE RHR BUMPER BRACKET (SIDE) (SN)	SERVICEABLE	\$66.66	\$0.00
1	REFLECTOR LHS REFLECTOR INNER (SN)	SERVICEABLE	\$99.77	\$0.00
1	REFLECTOR RHS REFLECTOR INNER (SN)	SERVICEABLE	\$99.77	\$0.00
1	EXHAUST SILENCER REAR (SN)	SERVICEABLE	\$2,966.22	\$0.00
1	DUAL CLAMP (SN)	NOT NECESSARY	\$73.11	\$0.00
1	REAR NUMBER PLATE (SN)	BENT	\$80.00	\$80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	SHORTED	\$400.00	\$400.00
			\$11,756.04	\$8,073.05
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	NOT NECESSARY	\$280.00	\$280.00
	B&P DIAGNOSIS AND PROGRAMMING		\$480.00	\$480.00
	LABOUR		\$4,200.00	\$1,680.00
	SPRAY PAINT		\$4,000.00	\$1,600.00
	R&R REAR W/SCREEN		\$840.00	\$840.00
	TRANSFER BOOT LID MECHANISM		\$840.00	\$420.00
	R&R REAR EXHAUST PIPE		\$840.00	\$0.00
	REAR WATER LEAK TEST		\$150.00	\$150.00
			\$11,630.00	\$5,450.00
GRAND TOTAL			\$23,386.04	\$13,523.05
	RECOMMENDED COST OF REPAIRS			\$13,523.05
Report Ref No: CS/FCI24060179/Rvh3e2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.