



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090430/Knp3e2
16 RAFFLES QUAY	Date:	07/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3313S	Veh. Inspected	SKW 9443U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008378MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	24/09/2024

### 2. Vehicle Details

Make & Model	TOYOTA CAMRY (A)	C.C	1998
Engine No.	6ARP090932	Year of Reg.	23/11/2015
Chassis No.	MR053DK5100104663	Colour	METALLIC BLACK
Odometer	137945 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	MICHELIN	8
L/H Front Tyre	215/55R17	MICHELIN	8
R/H Rear Tyre	215/55R17	MICHELIN	8
L/H Rear Tyre	215/55R17	MICHELIN	8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	21/09/2024	Inspection Date	24/09/2024
Survey held at	CHENG HOE MOTOR PL - BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days