11/18/24, 10:15 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090431/UPA3Q2

Date: 18/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0003403_02

Claimant Vehicle FBN4580T Insured Vehicle No: SNJ8006M

No:

Date of Loss: 15/09/2024 Nature of Claim: TP Claim No: MFL2024D0010876

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN4580T**

Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0432655 Reg. Date: 08/10/2018 (Man. Year: 2018) Chassis No: MH3UG0740J0125626

Colour: Black Odometer: 94220 km

Engine Capacity: 150 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Engine Modification: Handbrake (Serviceable): Yes Nο

CONDITION OF TYRES

Front Tyre Size: 70-90-17 Rear Tyre Size: 70-90-17 Front Left Side: Rear Left Side: Maxxis 6 mm Maxxis 6 mm

Front Right Side: $0 \, \text{mm}$ Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,035.00	1,240.50	2,794.50	69.26
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,040.00	200.00	840.00	80.77
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,075.00	1,440.50	3,634.50	71.62
	Approved Total (Overridden) (S\$)		1,150.00		
	Nett Amount (S\$)	5,075.00	1,150.00	3,925.00	77.34
	+ Loss of Use (3.0 x S\$	520.00/day) (S\$)	60.00		
	No	ett Liability (S\$)	1,210.00		

INSPECTION

Date of Assignment: 24/09/2024

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Date Inspected: 24/09/2024 Inspected At:

Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Condition

Renairer's

Amount

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Oct 2024)

Parts: N/A YAMAHA SNIPER T150 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN4580T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Oty Part No. Particulars

NO.	Qty	Part No.	Particulars	Condition	Repairers	Amount
1	2		*FRONT FORK TUBE ASSY	Repair	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Serviceable	225.00 FL	*- FL
3	1		*FRONT FENDER BRACKET	Repair	125.00 FL	*- FL
4	1		*FRONT SIDE COVER (MATT) - 1 SET	Cut	145.00 FL	*145.00 FL
5	1		*FRONT WHEEL RIM	Not Necessary	580.00 FL	*- FL
6	1		*FRONT RIM SHAFT	Cut	115.00 FL	*50.00 FL
7	1		*FRONT RIM BEARING	Serviceable	90.00 FL	*- FL
8	1		*FRONT BRAKE DISC	Not Necessary	235.00 FL	*- FL
9	1		*HANDLE BAR	Not Necessary	185.00 FL	*- FL
10	1		*HANDLE-BAR END (1 SET)	Not Necessary	155.00 FL	*- FL
11	1		*HAND GRIP (1 SET)	Not Necessary	85.00 FL	*- FL
12	1		*FRONT SIGNAL (1SET)	Cracked	140.00 FL	*80.00 FL
13	1		*PILOT LIGHTS	Cracked	380.00 FL	*185.00 FL
14	1		*FRONT HORN INNER COVER CENTRE MATT BLACK	Cracked	125.00 FL	*125.00 FL
15	1		*FRONT HORN INNER COVER	Missing	185.00 FL	*80.00 FL
16	1		*FAIRING ASSY (1SET)	Cracked	680.00 FL	*580.00 FL
17	1		*NUMBER PLATE (1 SET)	Not Necessary	50.00 FS	*- FS
18	1		*FORK OILS	Not Necessary	38.00 FS	*-FS
19	1		*FORK OILS SEALS	Not Necessary	30.00 FS	*- FS
20	1		*STEERING CONE (1 SET)	Not Necessary	56.00 FS	*-FS
21	1		*STICKER SET	Necessary	180.00 FS	*120.00 FS
F=Fra	nchise	part. S=SpcI	Nett. L=ListItemDisc.	2		
				Sub Total (S\$)	4,444.00	1,365.00
			- List Item Discount on L Iten	ns 10.00/10.00% (S\$)	409.00	124.50
				Total Parts (S\$)	4,035.00	1,240.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	TO PROVIDE TOWING SERVICE (LOD)	New	0.00	0.00		
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00		
3	TE REPAIR BODY FRAME	New	480.00	0.00		
4	TO PROVIDE LABOUR	New	480.00	200.00		
		Gross Labour Cost (S\$)	1,040.00	200.00		
Report was unsubmitted during this print-out						

< END OF ESTIMATES >