



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090434/Uqp3
16 RAFFLES QUAY	Date:	08/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3035P	Veh. Inspected	SKR 4426D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008347MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ CLA180 (A)	C.C	1595
Engine No.	27091030531543	Year of Reg.	09/02/2015
Chassis No.	WDD1173422N153032	Colour	PURPLE
Odometer	167270 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40ZR18	MICHELIN	6
L/H Front Tyre	225/40ZR18	MICHELIN	6
R/H Rear Tyre	225/40ZR18	MICHELIN	6
L/H Rear Tyre	225/40ZR18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/09/2024	Inspection Date	25/09/2024 (15:30)
Survey held at	YEW HOK AUTO SERVICES 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY SINAGPORE 417883		

5a. Remarks
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days