

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090435/KMA3Q2
Date: 03/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0009393_01
Claimant Vehicle No : SKV29Y Insured Vehicle No : GBL1465Z
Date of Loss: 16/09/2024 Nature of Claim: TP Claim No: MFL2024D0011719

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV29Y
Make & Model: TOYOTA HARRIER, 2.0 G GRADE (A) Engine No: 8ARZ100276
Reg. Date: 04/12/2017 (Man. Year: 2017) Chassis No: JTEKB3GH10J000966
Colour: Metallic Silver Odometer: 151431 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,380.60	4,735.12	2,645.48	35.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,400.00	600.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,380.60	6,135.12	3,245.48	34.60
Approved Total (Overridden) (S\$)		4,850.00		
Nett Amount (S\$)	9,380.60	4,850.00	4,530.60	48.30
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,477.25		
Global Sum Settlement (S\$)		5,400.00		

INSPECTION

Date of Assignment: 24/09/2024
Date Inspected: 24/09/2024 Inspected At: Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 G GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV29Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Buckled	924.10 FL	*924.10 FL
2	1		*REAR BUMPER BOTTOM (BLACK)	Dented / Cut	479.60 FL	*479.60 FL
3	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	183.60 FL	*- FL
4	2		*REAR BUMPER REVERSE SENSOR	Cut (1 PCS ONLY)	1,298.40 FL	*481.90 FL
5	2		*REAR BUMPER SIDE RETAINER	Serviceable	105.40 FL	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
7	1		*REAR BUMPER INNER FOAM	Cracked	154.70 FL	*154.70 FL
8	1		*REAR TAILGATE	Bent	2,827.60 FL	*2,827.60 FL
9	1		*REAR TAILGATE LH HARRIER EMBLEM	Necessary	84.90 FL	*84.90 FL
10	1		*REAR END PANEL	Buckled	1,260.70 FL	*1,260.70 FL
11	1		*REAR RH LOWER EXHAUST SILENCER	Repair	2,381.80 FL	*- FL
12	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,820.80	6,303.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,440.20	1,568.38
Total Parts (\$\$)	7,380.60	4,735.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES	New	800.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	800.00	600.00
3	TO CHECK WIRING AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE REFIT & RESET REVERSE SENSORS	New	80.00	60.00
5	TO REMOVE ,REFIT REAR UPHOLSTERY & ATTACHMENTS	New	120.00	60.00
6	TO REMOVE ,REFIT REAR RH LOWER EXHAUST SILENCER	New	80.00	0.00
7	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			2,000.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >