

ASS. REC. BY:

REF: FE21
W1Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Covanof 1368

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 877k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Soon: _____

Consistent? : Yes or No

Est. Repairs: 5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKV 294Yr Regn: 12 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy / HarrierC.G. 1998Colour: M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 151431

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STEK B36H10 J000986

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 235/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 16/9/24D.O.I. 24/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/9 11 Lm 8 48506 Cnlw

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

: Factors

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SKV29Y

Not Authorised
C/Ping & 4850h
Recovery After Painting
5 days

No.	Qty	List Items	
1	1	Rear bumper top	\$ Bu 924.10 ✓
2	1	Rear bumper bottom (Black)	\$ Del/Lm 479.60 ✓
3	2	Rear bumper side reflector	\$ Pn 183.60 X
4	1-2	Rear bumper reverse sensor 0481-80	\$ Lm 1,298.40 ✓
5	2	Rear bumper side retainer	\$ Sn 105.40 X
6	1 set	Rear bumper clips	\$ M 60.00 ✓
7	1	Rear bumper inner foam	\$ CM 154.70 ✓
8	1	Rear tailgate 67005-48350	\$ Pn 2,827.60 ✓
9	1	Rear tailgate LH "HARRIER" emblem	\$ M 84.90 ✓
10	1	Rear end panel 58307-48120	\$ Bu 1,260.70 ✓
11	1	Rear RH lower exhaust silencer	\$ R 2,381.80 X
			\$ 9,760.80
Less 25%			\$ 2,440.20
Total :			\$ 7,320.60

Special Nett Items

12	1 set	Rear end panel sealant	\$ 60.00 705n
----	-------	------------------------	---------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 800.00 600
2	To putty and spray Spray Paintings charges.	\$ 800.00 600
3	To check wirings and lightings.	\$ 40.00 200
4	To remove, refit & reset reverses sensors.	\$ 80.00 600
5	To remove, refit rear upholstery & attachments.	\$ 120.00 600
6	To remove, refit rear RH lower exhaust silencer.	\$ M 80.00 X
7	To supply and apply anti rust treatment	\$ 80.00 600
Total :		\$ 2,000.00

Total Parts and Labour : \$ 9,380.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurances Company

Acknowledged by Repairer
Signature:
Date: