

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	tionale Des Experts En	Automobile
MS	INCOME INSURAI	NCE LTD	Ref:	CS/INC24090441/Uvh3
	75 BRAS BASAH I		Date:	07/10/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBB 4414D	Veh. Inspected	GBK 7940J
	Policy No.	-	Coverage	0
	Claim No.	MT/1296175-002	Excess	\$0.00
	Assign From	JULIE	Assign Date	25/09/2024
2.		Vel	nicle Details	
	Make & Model	TOYOTA DYNA 150 5MT	c.c	2982
	Engine No.	1KDB050616	Year of Reg.	30/11/2020
	Chassis No.	JTFAT35Y80K215763	Colour	SILVER
	Odometer	96197 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	195R15	WINDFORCE	6
	L/H Front Tyre	195R15	WINDFORCE	6
	R/H Rear Tyre	155R12 (D)	WINDFORCE	6/6
	L/H Rear Tyre	155R12 (D)	WINDFORCE	6/6
4.	Description of Damages			
ΉE	VEHICLE SUSTAI	NED DAMAGES AT THE REAR O/S	PORTION.	
DAN	IAGES SEE DETAI	LS.		
5.	General Information			
	Accident Date	19/09/2024	Inspection Date	26/09/2024 (11:35)
	Survey held at	YEW HOK AUTO SERVICES 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY		
		SINAGPORE 417883	Remarks	
5a.				

Estimate Days of Repair