

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24090442/KVP3M4
Date: 16/06/2025

REFERENCE

Insured/Claimant: MOHAMMED FAIZ BIN JUNAIDI Policy No: MPC24P00055100
Date of Loss: 20/09/2024 Nature of Claim: OD Claim No: DMPC2401245H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNN6129J
Make & Model: MERCEDES-BENZ E250, 1.8 CGI CONVERTIBLE (A) Engine No: 27186030154000
Reg. Date: 20/12/2010 (Man. Year: 2010) Chassis No: WDD2074472F090289
Colour: Metallic Black Odometer: 156413 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$78,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 ZR18 Rear Tyre Size: 235/40 ZR18
Front Left Side: Continental 7 mm Rear Left Side: Continental 8 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,420.00	21,956.00	3,464.00	13.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	2,380.00	830.00	25.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,630.00	24,336.00	4,294.00	15.00
Approved Total (Overridden) (\$\$)		19,400.00		
- Excess (\$\$)	0.00	750.00	-750.00	
- Top-Up Amount (\$\$)	0.00	500.00	-500.00	
(\$\$)	28,630.00	18,150.00	10,480.00	36.60
+ GST 9.00/9.00% (\$\$)	2,576.70	1,633.50	943.20	36.60
Nett Amount (\$\$)	31,206.70	19,783.50	11,423.20	36.60

INSPECTION

Date of Assignment: 25/09/2024 Present Location: Vin's Motor Pte Ltd (Sin Ming)
VIN'S MOTOR PTE LTD
Date Inspected: 25/09/2024 Inspected At: 160 SIN MING DRIVE
#08-09, SIN MING AUTO CITY
SINGAPORE 575722
Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Jun 2025)	
Parts:	N/A	MERCEDES-BENZ E250 1.8 CGI CONVERTIBLE (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNN6129J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*RH DOOR (WCP)	Dented/Warped	3,900.00 F	*3,900.00 F
2	1	NA	*RH DOOR OUTER MOULDING (WCP)	Necessary	160.00 F	*160.00 F
3	1	NA	*RH DOOR INNER LOCK (WCP)	Repair	390.00 F	*- F
4	1	NA	*RH DOOR RUBBER (WCP)	Necessary	210.00 F	*210.00 F
5	1	NA	*RH SIDE SKIRT (WCP)	Distorted	920.00 F	*920.00 F
6	1	NA	*REAR RH FENDER (WCP)	Bent	3,200.00 F	*3,200.00 F
7	1	NA	*REAR RH FENDER OUTER CHROME MOULDING (WCP)	Dented	220.00 F	*220.00 F
8	1	NA	*REAR RH FENDER INNER TRIMBOARD (WCP)	Serviceable	680.00 F	*- F
9	1	NA	*REAR RH FENDER GLASS POWER WINDOW MOTOR (WCP)	Serviceable	470.00 F	*- F
10	1	NA	*REAR RH FENDER GLASS POWER WINDOW GEAR (WCP)	Serviceable	950.00 F	*- F
11	1	NA	*REAR RH FENDER INNER SHIELD (WCP)	Torn	160.00 F	*160.00 F
12	10	NA	*REAR RH FENDER INNER SHIELD CLIPS (WCP)	Necessary	60.00 F	*60.00 F
13	1	NA	*REAR RH RIM (WCP)	Cracked	1,400.00 F	*1,400.00 F
14	1	NA	*REAR RH SHOCK ABSORBER (WCP)	Bent	590.00 F	*590.00 F
15	1	NA	*REAR RH KNUCKLE ARM (WCP)	Bent	1,300.00 F	*1,300.00 F
16	1	NA	*REAR RH KNUCKLE WHEEL BEARING (WCP)	Necessary	250.00 F	*250.00 F
17	1	NA	*REAR RH TOP ARM (WCP)	Distorted	130.00 F	*130.00 F
18	1	NA	*REAR RH TOP CONTROL ARM (WCP)	Bent	180.00 F	*180.00 F
19	1	NA	*REAR RH LOWER ARM (WCP)	Bent	70.00 F	*70.00 F
20	1	NA	*REAR RH LOWER ARM COVER @ LOWER (WCP)	Serviceable	10.00 F	*- F
21	1	NA	*REAR RH LOWER ARM CONTROL (WCP)	Distorted	150.00 F	*150.00 F
22	1	NA	*REAR BUMPER (WCP)	Mtg Cracked	1,300.00 F	*1,300.00 F
23	1	NA	*REAR BUMPER RH SIDE RETAINER (WCP)	Cracked	20.00 F	*20.00 F
24	10	NA	*REAR BUMPER CLIPS (WCP)	Necessary	60.00 F	*60.00 F
25	1	NA	*REAR RH TYRE (70%) (SN)	Punctured	380.00 FS	*266.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	NA	*RH DOOR LOWER CHROME MOULDING (ACCESSORY)	Dented	350.00 FS	*350.00 FS
27	1	NA	*REAR BUMPER CHROME MOULDING (ACCESSORY)	Not Necessary	600.00 FS	*- FS
Supplementary #1						
28	1		*REAR RH SHOCK ABSORBER TOP MOULDING (WCP)	Cracked	50.00 F	*50.00 F
29	1		*REAR RH SHOCK ABSORBER DUST COVER (WCP)	Cracked	40.00 F	*40.00 F
30	1		*REAR RH SHOCK ABSORBER STOPPER (WCP)	Puncture	40.00 F	*40.00 F
31	1		*REAR RH DRIVE SHAFT (WCP)	Bent	2,100.00 F	*2,100.00 F
32	1		*REAR RH STABILIZER LINK (WCP)	Distorted	40.00 F	*40.00 F
33	1		*REAR RH LEVELLING (WCP)	Cracked	140.00 F	*140.00 F
34	1		*REAR CROSS MEMBER (WCP)	Bent	850.00 F	*850.00 F
35	4		*REAR CROSS MEMBER SCREW (WCP)	Necessary	160.00 F	*160.00 F
36	2		*REAR CROSS MEMBER BUSH (WCP)	Necessary	100.00 F	*100.00 F
37	1		*REAR EXHAUST SILENCER (WCP)	Bent	1,600.00 F	*1,600.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	23,230.00	20,016.00
+ Margin on L,N Items 10.00/10.00% (\$)	2,190.00	1,940.00
Total Parts (\$)	25,420.00	21,956.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
2	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	280.00	200.00
3	TO REMOVE AND REFIX SOFT TOP & SEAT CUSHION	New	800.00	500.00
4	TO REPAIR DAMAGES	New	880.00	800.00
5	TO SPRAY PAINTING	New	1,100.00	800.00
Gross Labour Cost (S\$)			3,210.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >