



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS3/LPC24090446/Evh3e2
300 BEACH ROAD	Date:	18/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	GBE 2963H	Veh. Inspected	SKS 9748L
Policy No.	-	Coverage	0
Claim No.	23/24/24/VC05/029918	Excess	\$0.00
Assign From	CHARMAINE	Assign Date	25/09/2024

2. Vehicle Details

Make & Model	MINI COOPER	C.C	1499
Engine No.	53269079B38A15A	Year of Reg.	18/05/2015
Chassis No.	WMWXS520502B37524	Colour	BLACK
Odometer	106574 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R16	PIRELLI	5
L/H Front Tyre	195/55 R16	PIRELLI	5
R/H Rear Tyre	195/55 R16	PIRELLI	5
L/H Rear Tyre	195/55 R16	PIRELLI	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/09/2024	Inspection Date	25/09/2024
Survey held at	25 KAKI BUKIT ROAD 4 #05-38 SYNERGY@KAKI BUKIT SINGAPORE 417800 - REPAIRER: ENTRUST MOTORWORKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days