



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060181/Tqp3e2
16 RAFFLES QUAY	Date:	29/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	SG 6136R
Policy No.	D-24102356MFBP	Coverage	0
Claim No.	D24005460MFBP	Excess	\$50,000.00
Assign From	JOANNE TAN	Assign Date	21/06/2024

2. Vehicle Details

Make & Model	MAN A95	C.C	10518
Engine No.	50352281665224	Year of Reg.	16/04/2019
Chassis No.	WMAA95ZZ7KF009077	Colour	GREEN
Odometer	485762 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	275/70 R22.5	FIRENZA	8
L/H Front Tyre	275/70 R22.5	FIRENZA	8
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/06/2024	Inspection Date	24/06/2024
Survey held at	MANDAI DEPOT - REPAIRER : TOWER TRANSIT SINGAPORE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE MARKET VALUE IS S\$340,000.00 (EST. AVERAGE)
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 20 Working Days