

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G8K22579

Yr Regn: 2020 / Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna

C.D. 2982

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 266406

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTAT35Y80K214452

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/75R15C

R: 155R12C

Rx Request

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06

mm

R/Bal. 06

mm

L/Bal. 06

mm

L/Bal. 06

mm

D.O.A. _____

D.O.I. 19/09/24

Survey held at HD Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG

COE Expiry :

Estimate given during : Yes ()

1st Survey : No ()

MV :

PV :

Nett :

546E

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

Report Format:

Report Form / R.P.C


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 18.09.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBK2257G**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 17.09.2024
TIME OF ACCIDENT : 15:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rebuilt</i>	1	\$ 727.10	\$ 727.10
2	FRONT BUMPER BRACKET <i>Best</i>	2	\$ 253.30	\$ 506.60
3	FRONT BUMPER FOGLAMP <i>den</i>	2	\$ 439.40	\$ 878.80
4	FRONT BUMPER FOGLAMP COVER <i>cut</i>	2	\$ 165.60	\$ 331.20
5	FRONT GRILLE <i>cut</i>	1	\$ 795.20	\$ 795.20
6	FRONT GRILLE LOGO <i>fu</i>	1	\$ 88.10	\$ 88.10
7	FRONT PANEL <i>Dented</i>	1	\$ 1,156.70	\$ 1,156.70
8	FRONT PANEL EMBLEM 'DYNA' <i>fu</i>	1	\$ 96.20	\$ 96.20
9	FRONT WINDSCREEN RUBBER <i>fu</i>	1	\$ 363.50	\$ 363.50
10	FRONT WINDSCREEN GLASS <i>Chipped</i>	1	\$ 1,532.70	\$ 1,532.70
11	FRONT WIPER PANEL (OUTER) <i>Dented</i>	1	\$ 476.20	\$ 476.20
12	FRONT WIPER PANEL (INNER) <i>Regrind</i>	1	\$ 798.30	\$ 798.30
13	FRONT WIPER BLADE <i>2</i>	2	\$ 72.60	\$ 145.20
14	FRONT WIPER ARM <i>MP</i>	2	\$ 179.80	\$ 359.60
15	FRONT WIPER LINKAGE <i>MP</i>	1	\$ 293.40	\$ 293.40
16	FRONT WIPER LINKAGE MOTOR <i>den</i>	1	\$ 678.80	\$ 678.80
17	FRONT NOZZLE <i>fu</i>	2	\$ 47.40	\$ 94.80
18	HEAD LAMP <i>ambled</i>	2	\$ 981.30	\$ 1,962.60
19	HEAD LAMP LOWER RUBBER <i>den</i>	2	\$ 47.20	\$ 94.40
20	FRONT CORNER PANEL <i>den</i>	2	\$ 329.80	\$ 659.60
21	FRONT CORNER TOP JOINT GARNISH <i>den</i>	2	\$ 26.40	\$ 52.80
22	FRONT CORNER SUPPORT PANEL BRACKET <i>den</i>	2	\$ 75.30	\$ 150.60

New/old

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK2257G**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 17.09.2024
 TIME OF ACCIDENT : 15:30 HOURS

23	SIDE MIRROR LH <i>Best new</i>	1	\$ 588.50	\$ 588.50	+
24	SIDE MIRROR STAND LH (AUTO) <i>New one</i>	1	\$ 678.40	\$ 678.40	✓
25	SIDE MIRROR TOP COVER LH <i>new</i>	1	\$ 32.60	\$ 32.60	+
26	SIDE MIRROR ROUND LH <i>new</i>	1	\$ 185.40	\$ 185.40	+
27	FRONT CABIN HINGE <i>new</i>	1	\$ 3,270.00	\$ 3,270.00	+
28	FRONT BRAKE PIPE <i>new</i>	4	\$ 323.00	\$ 1,292.00	+
29	AIR CON BLOWER MOTOR <i>new</i>	1	\$ 1,394.00	\$ 1,394.00	+
30	AIR CON COOLING COIL <i>new</i>	1	\$ 2,439.00	\$ 2,439.00	+
31	AIR CON PIPE <i>new</i>	2	\$ 475.00	\$ 950.00	+
32	AIR CON HOSE <i>new</i>	2	\$ 388.00	\$ 776.00	+
33	FRONT DASHBOARD <i>new</i>	1	\$ 1,250.40	\$ 1,250.40	+
34	FRONT DASHBOARD CENTER LOWER COVER GARNISH	1	\$ 396.40	\$ 396.40	+
35	FRONT DASHBOARD SWITCH CONTROL PANEL	1	\$ 764.30	\$ 764.30	+
36	FRONT DASHBOARD SIDE LOWER COVER GARNISH LH	1	\$ 568.20	\$ 568.20	+
37	FRONT WIRE HARNESS	1	\$ 7,200.70	\$ 7,200.70	+
38	WASHER TANK	1	\$ 168.30	\$ 168.30	+
39	AIR CON CONDENSER	1	\$ 987.70	\$ 987.70	+
40	AIR CON CONDENSER SUPPORT BRACKET	1	\$ 236.30	\$ 236.30	+
41	AIR CON CONDENSER FAN MOTOR C/W COWLING	1	\$ 429.80	\$ 429.80	+
42	AIR CON BLOWER	1	\$ 1,758.60	\$ 1,758.60	+
43	AIR CON COOLING COIL	1	\$ 2,379.20	\$ 2,379.20	+
44	AIR CON HEATER	1	\$ 983.80	\$ 983.80	+
45	AIR CON PIPE	2	\$ 396.50	\$ 793.00	+
46	FRONT DOOR STEP PANEL	2	\$ 302.50	\$ 605.00	+
47	TAILGATE <i>Dented</i>	1	\$ 1,370.00	\$ 1,370.00	✓
48	TAILGATE HINGE <i>2 pieces Best</i>	4	\$ 165.00	\$ 660.00	330
49	TAILGATE SIDE LOCK <i>new</i>	2	\$ 125.00	\$ 250.00	+
50	TAILGATE STOPPER RUBBER <i>LHA missing</i>	2	\$ 35.00	\$ 70.00	35
51	TAILGATE STOPPER BRACKET <i>P25</i>	2	\$ 175.00	\$ 350.00	+
52	TAILGATE STICKER 'TOYOTA' <i>new</i>	1	\$ 167.60	\$ 167.60	✓
53	SIDE GATE <i>P25</i>	2	\$ 1,968.90	\$ 3,937.80	+
54	SIDE GATE SAFETY LOCK <i>new</i>	2	\$ 132.10	\$ 264.20	+
55	TAIL LAMP <i>LHA at</i>	2	\$ 245.00	\$ 490.00	245

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK2257G**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 17.09.2024
 TIME OF ACCIDENT : 15:30 HOURS

56	TAIL LAMP SUPPORT BRACKET <i>new</i>	2	\$ 185.00	\$ 370.00	+
57	REAR STICKER 'DYNA' <i>new</i>	1	\$ 45.00	\$ 45.00	✓
58	REAR END PANEL <i>Deletd</i>	1	\$ 1,245.00	\$ 1,245.00	495
59	REAR CHASSIS MEMBER RH <i>Repair</i>	1	\$ 1,068.50	\$ 1,068.50	+

TOTAL PRICE \$ 52,658.10
 LESS 25% \$ 13,164.53
SUB TOTAL PRICE \$ 39,493.58

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	30
2	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	30
3	FRONT PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	60
4	DASHBOARD CLIP (SET) <i>229</i>	1	\$ 150.00	\$ 150.00	+
5	DASHBOARD CENTER GARNISH CLIP (SET) <i>for</i>	1	\$ 50.00	\$ 50.00	+
6	FRONT WINDSCREEN GLASS SEALANT <i>320</i>	1	\$ 80.00	\$ 80.00	40
7	FRONT WINDSCREEN GLASS INNER SEAL <i>320</i>	1	\$ 60.00	\$ 60.00	30
8	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	30
9	TAIL GATE ALUMINIUM COVER (SPECIAL TYPE) <i>Deletd</i>	1	\$ 680.00	\$ 680.00	350
10	TAIL GATE '70KM/H' STICKER <i>new</i>	1	\$ 40.00	\$ 40.00	15
11	SIDE GATE ALUMINIUM (SPECIAL TYPE) <i>new</i>	2	\$ 850.00	\$ 1,700.00	✓
12	SIDE GATE COMPANY STICKER (SPECIAL TYPE) <i>new</i>	2	\$ 380.00	\$ 760.00	✓
13	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
14	REAR STEP BRACKET <i>Best</i>	1	\$ 80.00	\$ 80.00	50
15	REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE) <i>new</i>	1	\$ 3,800.00	\$ 3,800.00	+
16	REVERSE SENSOR (SET) <i>Deletd</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 8,060.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,000.00	800
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,200.00	800
3	TO SPRAY TUFF COAT	\$ 250.00	40

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK2257G**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 17.09.2024
 TIME OF ACCIDENT : 15:30 HOURS

4	WIRING, BULB CHECKING	\$ 80.00	30
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	+
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	+
7	REFOCUS HEADLAMP BEAM	\$ 60.00	+
8	REMOVE AND REFIX AIRCON BLOWER, COOLING COIL, AIR CON CONDENSER AND REFILL AIRCON GAS	\$ 250.00	+
9	REMOVE AND REINSTALL DASHBOARD	\$ 650.00	+
10	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓
11	REMOVE AND REFIX FRONT VIDEO RECORDER	\$ 80.00	50
12	RESET RADIO SYSTEM	\$ 200.00	+
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	4

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,400.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	600
3	REMOVE AND REFIX REAR RAILING	\$ 350.00	+
4	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	50
5	REMOVE AND REFIX REAR FLOOR AUMINIUM	\$ 650.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBK2257G**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 17.09.2024
TIME OF ACCIDENT : 15:30 HOURS

6	REAR CHASSIS ALIGHMENT	\$	250.00	X
---	------------------------	----	--------	---

TOTAL \$ 9,530.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 47,553.58
TOTAL LABOUR COST : \$ 9,530.00
TOTAL REPAIR COST : \$ 57,083.58

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Action
1/S 19/09/24
10 Days