

Veh No: G B G 7086 X Yr Regn: 2017 Oct
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Hiace DX C.D. 2982
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 212860 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: KDH 2015 02 6 021
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 R15C
R: 195 R15C

Remark: Trench had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Mark Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/DHTSU/PIR/SUMI/
TOYO/YOKO or *Black hawk*

<u>Front</u>		<u>Rear</u>	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>17/09/23</u>	

*Survey held at J-Marq

Des. of Damages : Frt / Rear / O/S / N/S / U/G / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPALG
	COE Expiry :
	Estimate given during : Yes C ✓ 1st Survey : No C)
MV :	
PV :	
Nett:	

Date/Time, File Pass to?

☐	: Prel. Report
☐	: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) Date/Time, File, Return to?

2)

Add Fee: ☐ : Site Insp (\$

Interview - (3)

: Tech. Invs- (2)

Photos

1	Others
---	--------

Report Formed:

1. Wiederholung (Repetition)

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration NO: 201400246D
GST Reg. NO: 201400246D

17-Sep-24

Our ref : TP/5457/24

Day & Night Services Pte Ltd

RE : Estimate cost for vehicle no : GBG 7086X

1 pc	frt lh door <i>Dented</i>	\$	1,867.90
1 pc	frt lh door moulding <i>new</i>		+ 110.00
1 pc	frt lh wing mirror <i>broken new ?</i>		? 1212.10
1 pc	lh headlamp <i>lit</i>		2510.00
1 pc	frt bumper <i>red and</i>		✓ 773.20
1 pc	frt bumper lh retainer <i>new</i>		✓ 150.00
10 pcs	frt bumper clips <i>in</i>		✓ 50.00 <i>30</i>
1 pc	frt bumper lh fog lamp <i>?</i>		✓ 285.00
1 pc	frt bumper lh fog lamp cover <i>?</i>		? 66.50
1 pc	frt lh step garnish <i>new</i>		155.00
			7,179.70
less 25%			1,794.93
			5,384.78
1 pc	lh wing mirror cover <i>new</i>	snet	<i>80</i> 150.00
1 pc	frt lh door sticker <i>new</i>		✓ 25.00
Panel beating.			<i>400</i> 800.00
Spray painting.			<i>200</i> 800.00
Wiring.			✓ 30.00
Transfer door parts.			<i>60</i> 80.00
			7,269.78
Plus 9% GST			654.28
			7924.05

SD : seven thousand nine hundred twenty-four & cents five only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan C
h/s 17/09/24
042yr.