



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924		Ref: Date: Code:	CS/AGI24090453/Uqp3 04/10/2024 AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGB 2209J	Veh. Inspected	FW 17K	
Policy No.	P11099808R00	Coverage	0	
Claim No.	C10031856/JK	Excess	\$0.00	
Assign From	JANICE KOH	Assign Date	25/09/2024	
2. Vehicle Details				
Make & Model	YAMAHA NMAX 155	C.C	155	
Engine No.	G3L8E1871054	Year of Reg.	15/02/2024	
Chassis No.	MH3SG5680PK201333	Colour	GREEN	
Odometer	2628 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	110-70-13	IRC	9	
L/H Front Tyre				
R/H Rear Tyre	130-70-13	IRC	9	
L/H Rear Tyre				
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2024	Inspection Date	25/09/2024	
Survey held at	TEO SPRAY PAINTING BLK 6 DEFU LANE 10 DEFU IND PARK C #01-558 SINGAPORE 539187			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				