

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090455/UUA3Q2**Date:** 04/08/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0001733_01
Claimant Vehicle No : SNF5377H **Insured Vehicle No :** GBM5175D
Date of Loss: 24/09/2024 Nature of Claim: TP Claim No: MFL2024D0011264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF5377H**
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 CVT 2WD (M-LINE) (A) Engine No: 4B40JL4952
Reg. Date: 01/06/2022 (Man. Year: 2021) Chassis No: JMAXTGK1WNZ000146
Colour: White Odometer: 57310 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R16 Rear Tyre Size: 215/70 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,688.00	5,613.00	6,075.00	51.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,930.00	5,790.00	5,140.00	47.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,618.00	11,403.00	11,215.00	49.58
+ GST 9.00/9.00% (S\$)	2,035.62	1,026.27	1,009.35	49.58
Nett Amount (S\$)	24,653.62	12,429.27	12,224.35	49.58
+ Car Rental (7.0 x S\$100.00/day + 9.00% GST) (S\$)		763.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		13,219.52		

INSPECTION

Date of Assignment: 01/10/2024
Date Inspected: 01/10/2024 Inspected At: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Ubi)
330 UBI ROAD 3
Singapore 408650
Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2025)
Parts:	143	MITSUBISHI ECLIPSE CROSS 1.5 CVT 2WD (M-LINE) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF5377H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REVERSE SENSORS	Malfunction	220.00 FS	*220.00 FS
2	1		*REAR LICENCE PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
3	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
4	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
5	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
6	1		*GLASS TAILGATE WINDOW	Not Necessary	606.00 FS	*- FS
7	1		*DAM TAILGATE LWR	Necessary	13.00 FS	*13.00 FS
8	4		*SPACER ,TAILGATE	Necessary	32.00 FS	*32.00 FS
9	2		*STOPPER ,WINDSHIELD GLASS	Necessary	8.00 FS	*8.00 FS
10	4		*FASTENER WINDSHIELD	Necessary	32.00 FS	*32.00 FS
11	1		*MARK ,THREE-DIA	Necessary	64.00 FS	*64.00 FS
12	1		*MARK ECLIPSE	Necessary	71.00 FS	*71.00 FS
13	1		*MARK CROSS	Necessary	53.00 FS	*53.00 FS
14	1		*GARNISH ,TAILGATE	Cracked	779.00 FS	*779.00 FS
15	1		*PANEL ASSY ,TAILGATE	Badly Dented	1,099.00 FS	*1,099.00 FS
16	1		*GAS SPRING TAILGATE LH	Not Necessary	156.00 FS	*- FS
17	1		*GAS SPRING TAILGATE RH	Not Necessary	156.00 FS	*- FS
18	1		*HANDLE ,TAILGATE LOCK RLSE	Serviceable	213.00 FS	*- FS
19	1		*LATCH ,TAILGATE	Not Necessary	234.00 FS	*- FS
20	1		*STRIKER ,TAILGATE LATCH	Not Necessary	21.00 FS	*- FS
21	1		*TRIM TAILGATE LWR	Not Necessary	421.00 FS	*- FS
22	1		*W/STRIP ,TAILGATE OPENING	Twisted	198.00 FS	*198.00 FS
23	2		*LAMP ASSY ,LICENSE PLATE	Not Necessary	72.00 FS	*- FS
24	1		*OTR LAMP ASSY ,COMB ,RR LH	Not Necessary	552.00 FS	*- FS
25	1		*OTR LAMP ASSY ,COMB ,RR RH	Not Necessary	552.00 FS	*- FS
26	1		*INR LAMP ASSY TAIL LH	Not Necessary	471.00 FS	*- FS
27	1		*INR LAMP ASSY TAIL RH	Not Necessary	471.00 FS	*- FS
28	1		*FACE RR BUMPER	Dented	675.00 FS	*675.00 FS
29	1		*EXTENSION RR BUMPER	Dented	197.00 FS	*197.00 FS
30	1		*BRKT ,R/BMPR FACE SIDE LH	Bent	46.00 FS	*46.00 FS
31	1		*BRKT ,R/BMPR FACE SIDE RH	Bent	46.00 FS	*46.00 FS
32	5		*CLIP ENG ROOM COVER	Necessary	10.00 FS	*10.00 FS
33	5		*CLIP FR BUMPER	Necessary	20.00 FS	*20.00 FS
34	1		*REFLECTOR ,TAIL LAMP LH	Cracked	73.00 FS	*73.00 FS
35	1		*LAMP ASSY ,FOG RR RH	Cracked	250.00 FS	*250.00 FS
36	1		*CORE ,RR BUMPER LH	Cracked	36.00 FS	*36.00 FS
37	1		*CORE ,RR BUMPER RH	Cracked	36.00 FS	*36.00 FS
38	1		*REINFORCEMENT ,RR BUMPER	Bent	521.00 FS	*521.00 FS
39	1		*BRACKET ,RR REINFORCEMENT	O/S Twisted	60.00 FS	*30.00 FS
40	1		*BUZZER ,KEYLESS OPERATIO RR	Not Necessary	96.00 FS	*- FS
41	1		*ANT ,KEYLESS OPERATION RR	Not Necessary	102.00 FS	*- FS
42	1		*PANEL RR END	Dented	486.00 FS	*486.00 FS
43	1		*TRIM RR END	Twisted	124.00 FS	*124.00 FS
44	1		*LID CARGO FLOOR BOX	Not Necessary	265.00 FS	*- FS
45	1		*BOX CARGO FLOOR LH	Not Necessary	200.00 FS	*- FS
46	1		*BOX CARGO FLOOR RH	Not Necessary	200.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TRIM ,QTR ,LWR LH	Not Necessary	287.00 FS	*- FS
48	1		*TRIM ,QTR ,LWR RH	Not Necessary	287.00 FS	*- FS
49	1		*MOULDING RR WHEEL ARCH LH	Torn	162.00 FS	*162.00 FS
50	1		*MOULDING RR WHEEL ARCH RH	Torn	162.00 FS	*162.00 FS
51	1		*SHIELD RR WHEEL RR LH	Not Necessary	41.00 FS	*- FS
52	1		*SHIELD RR WHEEL RR RH	Not Necessary	41.00 FS	*- FS
53	1		*MUFFLER ,EXHAUST MAIN	Not Necessary	571.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)**11,688.00****5,613.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE	New	280.00	280.00
2	TO CHECK WIRING AND ELECTRICAL SYSTEM	New	100.00	80.00
3	TO REMOVE & REPLACE TAILGATE GLASS ,DAMS ,SPACERS & FASTENERS	New	320.00	320.00
4	TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS	New	280.00	0.00
5	TO TRANSFER TAILGATE COMPONENTS & MECHANISM	New	640.00	320.00
6	TO REMOVE & REINSTALL TRIMS ,CARPETS ,FLOOR BOARDS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
7	TO REPLACE LOGO EMBLEM ,T/GATE PNL & GARNISH LH/RH GAS SPRING ,LATCH ,LOCK HANDE ,STRIKER T/GATE LWR TRIM ,W/STRIP ,PLATE LAMPS OTR & INR TAILLAMPS ,REAR BUMPER ,EXTN BPR ,SIDE BRACKETS CLIPS ,LH RFLTR LAMP ,RHR FOG LAMP ,LH/RH CORE BPR REINFORCEMENT & BRACKET ANTENNA BUZZER ETC TO CUT & WELD REAR END PANEL,TO REPAIR REAR FLOOR STRAIGHTEN ,REFORM ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,480.00	2,240.00
8	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE PNL,UPPER REAR BUMPER ,REAR END PANEL ,REAR FLOOR)	New	2,750.00	1,650.00
9	TO CHECK TEST REFIT REVERSE SENSOR	New	100.00	80.00
10	TO REMOVE & REPLACE EXHAUST MUFFLER	New	640.00	0.00
11	TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS	New	100.00	100.00
12	TO APPLY BODY SEALANT ON NEW PANELS	New	300.00	200.00
13	TO APPLY ANTI-CORROSION ON AFFECTED AREAS	New	300.00	200.00
Gross Labour Cost (\$\$)			10,930.00	5,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >