



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

not about  
near  
1/10/24  
the ph. 64739722  
7 days

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chua Tian Seong	Cust No/Name /Mr Chua Tian Seong
146 Rivervale Drive	Reg No/Reg Date SNF5377H / 01/06/2022
#06-505	Date In/Mileage 24/09/2024/ 57309
Singapore 540146	Chassis No JMAXTGK1WNZ000146
Contact No Mobile: 96641766	Engine No 4B40JL4952
	Make/Model MIT/ECLIPSE CROSS CLASSIC (T04)
	Colour/Trim W85 WHITE DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/09/2024/ 13:52	REN	979 / Renemer Ramirez Bag	26917
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 24/09/2024 ALONG MANDAI ROAD					
OWNER CLAIMING THIRD PARTY CLAIM					
REQUIRED REPLACEMENT VEHICLE					
TP#: GBM5175D TP INS: INDIA INT'L INSURANCE					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE					
A 90000001					80 100.00
TO CHECK WIRING AND ELECTRICAL SYSTEM					
E PNT88000					320.00
TO REMOVE & REPLACE TAILGATE GLASS,DAMS,SPACERS & FASTENERS					
E PNT88000					71 280.00
TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS					
E PNT88000					320 640.00
TO TRANSFER TAILGATE COMPONENTS & MECHANISM					
E PNT88000					320 640.00
TO REMOVE & RE-INSTALL TRIMS,CARPETS,FLOOR BOARDS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000					2280 4480.00
TO REPLACE LOGO,EMBLEM,T/GATE PNL & GARNISH,LH/RH GAS SPRING,LATCH, LOCK HANDLE,STRIKER,T/GATE LWR TRIM,W/STRIP,PLATE LAMPS,OTR & INR TAILLAMPS,REAR BUMPER,EXTN BPR,SIDE BRACKETS,CLIPS,LH RFLTR LAMP, RHR FOG LAMP,LH/RH CORE BPR,REINFORCEMENT & BRACKET,ANTENNA,BUZZER,ETC -TO CUT & WELD REAR END PANEL -TO REPAIR REAR FLOOR STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					1650 2750.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE PNL,UPPER REAR BUMPER,REAR END PANEL,REAR FLOOR)					
E PNT88000					80 100.00
TO CHECK,TEST,REFIT REVERSE SENSOR					
E PNT88000					220.00
TO SUPPLY ONE SET REVERSE SENSORS					
E PNT88000					640.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

## Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chua Tian Seong  146 Rivervale Drive #06-505 Singapore 540146  Contact No Mobile: 96641766	Cust No/Name /Mr Chua Tian Seong Reg No/Reg Date SNF5377H / 01/06/2022 Date In/Mileage 24/09/2024/ 57309 Chassis No JMAXTGK1WNZ000146 Engine No 4B40JL4952 Make/Model MIT/ECLIPSE CROSS CLASSIC (T04) Colour/Trim W85 WHITE DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/09/2024/ 13:52	REN	979 / Renemer Ramirez Bag	26917
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
TO REMOVE & REPLACE EXHAUST MUFFLER					
M SUNDRY					50.00
TO SUPPLY REAR LICENSE PLATE WITH FRAME					
M SUNDRY					100.00
TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS					
M SUNDRY					300.00
TO APPLY BODY SEALANT ON NEW PANELS					
M SUNDRY					300.00
TO APPLY ANTI-CORROSION ON AFFECTED AREAS					
M SUNDRY					50.00
TO SUPPLY MIVEC EMBLEM					
M SUNDRY					50.00
TO SUPPLY C&C BADGE					
M SUNDRY					50.00
SUNDRIES					
M GLASS, TAILGATE WINDOW		1.00	606.00	00.00	606.00
M DAM, TAILGATE, LWR		1.00	13.00	00.00	13.00
M SPACER, TAILGATE		4.00	8.00	00.00	32.00
M STOPPER, WINDSHIELD GLASS		2.00	4.00	00.00	8.00
M FASTENER, WINDSHIELD		4.00	8.00	00.00	32.00
M MARK, THREE-DIA		1.00	64.00	00.00	64.00
M MARK, ECLIPSE		1.00	71.00	00.00	71.00
M MARK, CROSS		1.00	53.00	00.00	53.00
M GARNISH, TAILGATE		1.00	779.00	00.00	779.00
M PANEL ASSY, TAILGATE		1.00	1099.00	00.00	1099.00
M GAS SPRING, TAILGATE, LH		1.00	156.00	00.00	156.00
M GAS SPRING, TAILGATE, RH		1.00	156.00	00.00	156.00
M HANDLE, TAILGATE LOCK RLSE		1.00	213.00	00.00	213.00
M LATCH, TAILGATE		1.00	234.00	00.00	234.00
M STRIKER, TAILGATE LATCH		1.00	21.00	00.00	21.00
M TRIM, TAILGATE, LWR		1.00	421.00	00.00	421.00
M W/STRIP, TAILGATE OPENING		1.00	198.00	00.00	198.00
M LAMP ASSY, LICENSE PLATE		2.00	36.00	00.00	72.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

## Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chua Tian Seong	Cust No/Name /Mr Chua Tian Seong
146 Rivervale Drive	Reg No/Reg Date SNF5377H / 01/06/2022
#06-505	Date In/Mileage 24/09/2024/ 57309
Singapore 540146	Chassis No JMAXTGK1WNZ000146
Contact No Mobile: 96641766	Engine No 4B40JL4952
	Make/Model MIT/ECLIPSE CROSS CLASSIC (T04)
	Colour/Trim W85 WHITE DIAMOND / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/09/2024/ 13:52	REN	979 / Renemer Ramirez Bag	26917
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M OTR LAMP ASSY, COMB, RR LH 11		1.00	552.00	00.00	552.00 X
M OTR LAMP ASSY, COMB, RR RH 11		1.00	552.00	00.00	552.00 X
M INR LAMP ASSY, TAIL, LH 11		1.00	471.00	00.00	471.00 X
M INR LAMP ASSY, TAIL, RH 11		1.00	471.00	00.00	471.00 X
M FACE, RR BUMPER 11		1.00	675.00	00.00	675.00
M EXTENSION, RR BUMPER 11		1.00	197.00	00.00	197.00
M BRKT, R/BMPR FACE SIDE, LH 11		1.00	46.00	00.00	46.00
M BRKT, R/BMPR FACE SIDE, RH 11		1.00	46.00	00.00	46.00
M CLIP, ENG ROOM COVER 11		5.00	2.00	00.00	10.00
M CLIP, FR BUMPER 11		5.00	4.00	00.00	20.00
M REFLECTOR, TAIL LAMP, LH 11		1.00	73.00	00.00	73.00
M LAMP ASSY, FOG, RR RH 11		1.00	250.00	00.00	250.00
M CORE, RR BUMPER LH 11		1.00	36.00	00.00	36.00
M CORE, RR BUMPER RH 11		1.00	36.00	00.00	36.00
M REINFORCEMENT, RR BUMPER 11		1.00	521.00	00.00	521.00
M BRACKET, RR REINFORCEMENT 11		1.00	30.00	00.00	60.00
M BUZZER, KEYLESS OPERATIO, RR 11		1.00	96.00	00.00	96.00
M ANT, KEYLESS OPERATION, RR 11		1.00	102.00	00.00	102.00
M PANEL, RR END 11		1.00	486.00	00.00	486.00
M TRIM, RR END 11		1.00	124.00	00.00	124.00
M LID, CARGO FLOOR BOX 11		1.00	265.00	00.00	265.00
M BOX, CARGO FLOOR, LH 11		1.00	200.00	00.00	200.00
M BOX, CARGO FLOOR, RH 11		1.00	200.00	00.00	200.00
M TRIM, QTR, LWR LH 11		1.00	287.00	00.00	287.00
M TRIM, QTR, LWR RH 11		1.00	287.00	00.00	287.00
M MOULDING, RR WHEEL ARCH, LH 11		1.00	162.00	00.00	162.00
M MOULDING, RR WHEEL ARCH, RH 11		1.00	162.00	00.00	162.00
M SHIELD, RR WHEEL, RR LH 11		1.00	41.00	00.00	41.00
M SHIELD, RR WHEEL, RR RH 11		1.00	41.00	00.00	41.00
M MUFFLER, EXHAUST MAIN 11		1.00	571.00	00.00	571.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Authorized signatory and company stamp

Acknowledged by Repairer  
Signature

Nett 22,618.00  
9% GST on 22618.00 2035.62  
Total Payable 24,653.62

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.