

ASS. REC. BY:

REF:

SMO/

CS/SMO24090457/Knp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value: \$24K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PKX 83618Yr Regn: 12, 15Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Bmw116d

C.C.

1496Colour: M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 171684

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAIV72050V250362Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 225/40R18

R: _____

 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 17/9/24D.O.I. 2/10/2024

Survey held at _____

Des. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Eti not ready

7/10

11 Lm @ 2400k Colour (Red, \$ 2528.20, 51%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Lian Her Motor Works

Blk 5034 #01-337 Ang Mo Kio Industrial Pk 2 Singapore 569537
Tel: 64817221

Fax: 64816131

Yoong Weng Kwai
Blk 210B Punggol Place
08 - 1202
Singapore 822210

Not Withheld
11 Lyr @ 2400p
Assembly After Paint
3 days

Vehicle No : SKX 8361 Z
Make : BMW 116D
Year :

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bumper	<i>photo 1250</i>
1 pc	Front bumper reinforcement	<i>repair</i>
1 pc	Front bumper sponge	<i>photo</i>
1 pc	Front bumper lower grille	<i>photo</i>
1 pc	Front bumper lower garnish	<i>photo</i>
1 pc	Front no plate holder	<i>photo</i>
2 pcs	Front grille	<i>photo C 212</i>
1 pc	Front radiator support garnish	<i>photo</i>
1 pc	Front support	<i>repair</i>

<i>Buclru</i>		
		\$1,250.00 ✓
<i>R</i>		\$550.00 ✗
<i>CM</i>		\$118.00 ✓
<i>CM</i>		\$195.00 ✓
<i>CM</i>		\$285.00 ✓
<i>RCI</i>		\$95.00 ✓
<i>CM</i>	\$285.00	\$570.00 ✓
<i>CM</i>		\$185.00 ✓
<i>R</i>		\$650.00 ✗
		\$3,898.00
Less 10 %		\$389.80
		\$3,508.20

S Nett

1 pc	Front no plate (chrome version)
------	---------------------------------

RCI \$80.00 *45sm*

Labour Charges

Remove/renew the above parts including knocking and welding.

\$700.00 *400l*

To putty & spray paint on front accident affected portion.

\$600.00 *250l*

Check/reconnect wiring.

\$40.00 *20l*

Total \$4,928.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: