



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKA 8091Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WING MIRROR HOUSING	CRACKED	\$1,694.40	\$1,694.40
1	FRONT WING MIRROR OUTER COVER	MISSING	\$62.60	\$62.60
1	FRONT WING MIRROR SIGNAL LAMP	CRACKED	\$45.40	\$45.40
1	FRONT WING MIRROR GLASS	CRACKED	\$105.50	\$105.50
	LESS 25.00% DISCOUNT		(\$476.98)	(\$476.98)
			\$1,430.92	\$1,430.92

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR.		\$300.00	\$80.00
	SPRAY PAINTING.		\$300.00	\$80.00
	REWIRE.		\$50.00	\$20.00
			\$650.00	\$180.00

GRAND TOTAL	\$2,080.92	\$1,610.92
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,250.00
---	--	-------------------

Report Ref No: CS/SMO24060182/Knh3m4

KSC

KENNETH KONG SENG CHEONG