



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24060182/Knh3m4
50 RAFFLES PLACE #03-03	Date:	21/06/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 5963B	Veh. Inspected	SKA 8091Z
Policy No.	-	Coverage	0
Claim No.	CMTD2402049/SYH	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	21/06/2024

2. Vehicle Details

Make & Model	TOYOTA CAMRY 2.4 AUTO ABS AIRBAG	C.C	2362
Engine No.	2AZE136436	Year of Reg.	10/06/2009
Chassis No.	MR053BK4007034763	Colour	METALLIC GOLD
Odometer	866253 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	TOURADOR	6
L/H Front Tyre	215/60R16	TOURADOR	6
R/H Rear Tyre	215/60R16	TOURADOR	6
L/H Rear Tyre	215/60R16	TOURADOR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/06/2024	Inspection Date	25/06/2024
Survey held at	160 SIN MING AUTOCITY #06-21 SINGAPORE 575722 - ENG SHING MECHANICAL WORKS		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days