10/9/24, 10:43 AM Adjuster Report

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No:

CS/AIG24090466/ENH3E2

Singapore 079120

Date:

09/10/2024

REFERENCE

Insured/Claimant: Date of Loss:

VICKRUM MUTHSAMY P

Policy No: Nature of Claim: 1800080628

6788532080SG Claim No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**SDB9330E** 

Make & Model:

AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)

Engine No: Chassis No:

OD

CVK061246

Reg. Date:

12/07/2018 (Man. Year: 2018)

Odometer:

WAUZZZF41JA165172 103836 km

Colour:

Silver 1984 cc

27/08/2024

Engine Capacity: Market Value/New Car Price: S\$82,000.00

Sum Insured (S\$):

**Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Front Right Side:

Steering (Serviceable): **Engine Modification:** 

Yes No

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

205/60 R16 Continental 4 mm

Continental 4 mm

Yes

Rear Tyre Size: Rear Left Side: Rear Right Side: 205/60 R16

Continental 4 mm Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,664.00	4,078.00	2,586.00	38.81
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,622.00	2,722.00	1,900.00	41.11
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	11,286.00	6,800.00	4,486.00	39.75
	- Excess (S\$)	3,100.00	3,100.00	0.00	0.00
	(S\$)	8,186.00	3,700.00	4,486.00	54.80
	+ GST 9.00/9.00% (S\$)	736.74	333.00	403.74	54.80
	Nett Amount (S\$)	8,922.74	4,033.00	4,889.74	54.80

**INSPECTION** 

Date of Assignment:

26/09/2024

Premium Automobiles Pte Ltd (UBI)

Date Inspected:

27/09/2024

Inspected At:

Singapore 408699

55 Ubi Road 1

Estimated Period of Repair:

4.0 days

**HUEY YON** 

**CHEN TSUE YEE** Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$986.00 NETT)

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	3,647.00 FS	*3,647.00 FS
2	1		*FRONT DOOR SEAL, OUTER LH	Necessary	275.00 FS	*275.00 FS
3	1		*BONDING AGENT	Necessary	54.00 FS	*54.00 FS
4	1		*CLEANING SOLUTION	Necessary	92.00 FS	*92.00 FS
5	1		*APPLICATOR	Necessary	10.00 FS	*10.00 FS
6	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	1,179.00 FS	*- FS
7	1		*FRONT DOOR CATCH - LH	* Check	131.00 FS	*- FS
8	1		*FRONT DOOR HANDLE TRIM PLATE	Not Necessary	166.00 FS	*- FS
9	1		*FRONT DOOR HANDLE, EXTERIOR	Not Necessary	53.00 FS	*- FS
10	2		*FRONT DOOR HANDLE UNDERLAY - LH FRONT / REAR	Not Necessary	10.00 FS	*- FS
11	1		*FRONT DOOR MOUNTING BAR - LH	* Check	206.00 FS	*- FS
12	1		*FRONT DOOR HANDLE HOUSING - LH	Not Necessary	12.00 FS	*- FS
13	1		*FRONT SILL TRIM STRIP - LH	* Check	149.00 FS	*- FS
14	1		*STONECHIP	Repair	180.00 FS	*- FS
15	1		*SUNDRIES	* Check	500.00 FS	*- FS
F=Fra	ınchise	part. S=SpcI	Nett.	,		
				Total Parts (S\$)	6,664.00	4,078.00
			Report was unsubmitted during this prir			

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE AND TRANSFER LHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	350.00
2	TO DISMANTLE AND RENEW LHS FRONT FENDER. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,750.00	500.00
3	TO RESPRAY LHS FRONT FENDER AND LHS SILL PANEL	New	1,750.00	1,100.00
4	TO CARRY OUT CHIP TREATMENT AND SEALANT WORK ON LHS SILL PANEL	New	480.00	480.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
	Gross Labou	r Cost (S\$)	4,622.00	2,722.00
	Report was unsubmitted during this pri	int-out.		

< END OF ESTIMATES >