



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNH 3836C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT/TORN	\$3,215.60	\$1,866.21
1	FRONT BUMPER RETAINER LH	CRACKED	\$327.00	\$66.50
1	FRONT HEADLAMP LH	SCRATCHED/CRACKED	\$5,434.74	\$5,434.74
1	FRONT HEADLAMP BRACKET LH	NOT NECESSARY	\$552.00	\$0.00
1	FRONT FOG LAMP LH	NOT NECESSARY	\$267.00	\$0.00
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	\$2,245.00	\$0.00
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	\$475.00	\$0.00
1	FRONT AIR SUSPENSION (AIR MATIC) LH	NOT NECESSARY	\$3,754.00	\$0.00
1	FRONT CONTRAL ARM LH	BENT/TWISTED	\$854.00	\$699.20
1	FRONT TIE ROD END LH	NOT NECESSARY	\$385.00	\$0.00
1	FRONT TIE ROD LH	NOT NECESSARY	\$385.00	\$0.00
1	FRONT LOWER ARM LH	SERVICEABLE	\$958.50	\$0.00
1	FRONT KNUCKLE LH	BENT	\$1,250.00	\$1,250.00
1	FRONT WHEEL BEARING LH	NECESSARY	\$488.00	\$488.00
1	FRONT ANTI ROLL BAR LINK LH	NOT NECESSARY	\$205.00	\$0.00
	LESS 5.00 / 10.00% DISCOUNT		(\$1,039.79)	(\$980.47)
			\$19,756.05	\$8,824.18

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH RIM (SN)	WARPED/BENT	\$1,500.00	\$900.00
1	FRONT SENSOR (SN)	SERVICEABLE	\$1,200.00	\$0.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$50.00
1	SET FRONT FENDER INNERSHIELD CLIPS (SN)	NOT NECESSARY	\$80.00	\$0.00
			\$2,830.00	\$950.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK FRONT WIRING AND LIGHTING SYSTEM		\$100.00	\$20.00
	REMOVE AND REFIX FRONT SENSOR		\$120.00	\$40.00
	TO CONDUCT WHEEL ALIGNMENT		\$150.00	\$100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH		\$1,400.00	\$300.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,400.00	\$450.00
	APPLY ANTI RUST ON AFFECTED AREAS	NOT NECESSARY	\$100.00	\$0.00
			\$3,270.00	\$910.00
GRAND TOTAL			\$25,856.05	\$10,684.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$8,500.00
Report Ref No: CS/AGI24060183/Uqh3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser