



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090473/Uqp3m4
16 RAFFLES QUAY	Date:	29/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3132S	Veh. Inspected	SBU 4626J
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008472MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	26/09/2024

### 2. Vehicle Details

Make & Model	MAZDA MX5 M5 (M)	C.C	1598
Engine No.	B6786565	Year of Reg.	05/06/1992
Chassis No.	JMONA306100103242	Colour	MAROON
Odometer	246073 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/50ZR15	PROXES	6
L/H Front Tyre	205/50ZR15	PROXES	6
R/H Rear Tyre	205/50ZR15	PROXES	6
L/H Rear Tyre	205/50ZR15	PROXES	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	25/09/2024	Inspection Date	02/10/2024
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days