



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMU 1093K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BONNET	TO REPAIR SEE LABOUR	\$1,297.70	\$0.00
1	BONNET LOCK	TO REPAIR SEE LABOUR	\$188.00	\$0.00
1	BONNET HEAT INSULATOR	SERVICEABLE	\$389.20	\$0.00
10	BONNET HEAT INSULATOR CLIP	NOT NECESSARY	\$60.00	\$0.00
1	BONNET HINGE LH	DISTORTED	\$81.80	\$81.80
1	BONNET HINGE RH	DISTORTED	\$81.80	\$81.80
1	HEADLAMP LH	CRACKED	\$1,873.40	\$1,873.40
1	FRONT SUPPORT PANEL (COMPLETE)	TO REPAIR SEE LABOUR	\$1,532.50	\$0.00
1	FRONT SUPPORT TOP GARNISH	SERVICEABLE	\$379.80	\$0.00
1	FRONT BUMPER	BENT/CRACKED	\$761.80	\$761.80
10	FRONT BUMPER CLIP	NECESSARY	\$60.00	\$60.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$615.60	\$0.00
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	\$153.50	\$153.50
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	\$153.50	\$0.00
1	FRONT BUMPER BRACKET LH	SERVICEABLE	\$353.70	\$0.00
1	FRONT BUMPER BRACKET RH	SERVICEABLE	\$353.70	\$0.00
1	FRONT BUMPER SPONGE (NPA)	SERVICEABLE	\$0.00	\$0.00
1	FRONT BUMPER UPPER GRILLE	SERVICEABLE	\$99.00	\$0.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	\$377.00	\$377.00
1	FRONT BUMPER TOW COVER	MISSING	\$126.10	\$126.10
1	FOG LAMP LH	MTG CRACKED	\$450.00	\$450.00
1	LH FRONT FENDER	BUCKLED	\$1,162.50	\$1,162.50
1	LH FRONT FENDER UNDERSHIELD	CRACKED	\$262.10	\$262.10
10	LH FRONT FENDER UNDERSHIELD CLIP	NECESSARY	\$50.00	\$50.00
1	RH FRONT FENDER QUARTER GARNISH	MISSING	\$57.20	\$57.20
1	HEADLAMP PANEL LH (ADDITIONAL)	TO REPAIR SEE LABOUR	\$109.40	\$0.00
1	FRONT BUMPER GARNISH LH (ADDITIONAL)	CRACKED	\$103.50	\$103.50
1	FOG LAMP COVER LH (ADDITIONAL)	DENTED	\$122.30	\$122.30
1	FOG LAMP GARNISH LH (NPA) (ADDITIONAL)	SERVICEABLE	\$0.00	\$0.00
1	AIR GUARD LH (ADDITIONAL)	CRACKED	\$67.50	\$67.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LHF RIM (ADDITIONAL)	DENTED	\$2,687.30	\$2,687.30
	LESS 25.00% DISCOUNT		(\$3,502.48)	(\$2,119.45)
			\$10,507.42	\$6,358.35

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT SENSOR (SN)	CUT	\$200.00	\$100.00
			\$200.00	\$100.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET, FRONT BUMPER, SUPPORT PANEL, LHF FENDER, LHF DOOR). INCLUSIVE OF THE REPAIR OF BONNET, BONNET LOCK, FRONT SUPPORT PANEL (COMPLETE), FRONT BUMPER REINFORCEMENT AND HEADLAMP PANEL LH		\$1,200.00	\$500.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET, FRONT BUMPER, SUPPORT PANEL, LHF FENDER, LHF DOOR)		\$1,200.00	\$600.00
	TO CHECK WIRING, FOCUS HEADLAMP		\$50.00	\$20.00
	TO REMOVE & REFIT RADIATOR TO ASSIST WORK LOAD	NOT NECESSARY	\$150.00	\$0.00
	TO REMOVE & REFIT AIRCON CONDENSOR TO ASSIST WORK LOAD, TO TOP UP A/C GAS	NOT NECESSARY	\$150.00	\$0.00
	TO DO WHEEL ALIGNMENT		\$120.00	\$60.00
	TO TUFF COAT		\$150.00	\$30.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	NOT NECESSARY	\$120.00	\$0.00
	TO REMOVE & REFIT FRONT SENSOR		\$120.00	\$50.00
			\$3,260.00	\$1,260.00

GRAND TOTAL		\$13,967.42	\$7,718.35
	RECOMMENDED COST OF REPAIRS		\$7,718.35
Report Ref No: CS/LAW24090482/Knp3e2			

KSC

KENNETH KONG SENG CHEONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.