

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliate data Foldonation Internationals Des Formata For Automobile | | | | | |
|--|--|--|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| MS | | K WILLAN SINGAPORE LLP | Ref: | CS/LAW24090482/Knp3e2 | |
| | SINGAPORE 0486 | E, #24-01, OXLEY @ RAFFLES 22 | Date: | 18/10/2024 | |
| | | | Code: | L181 | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | TRACTOR | Veh. Inspected | SMU 1093K | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | 67925-463 | Excess | \$0.00 | |
| | Assign From | ELISSA | Assign Date | 27/09/2024 | |
| 2. Vehicle Details | | | | | |
| | Make & Model | TOYOTA VIOS (A) | C.C | 1496 | |
| | Engine No. | 2NR5435389 | Year of Reg. | 29/07/2020 | |
| | Chassis No. | MR2B23F3501203488 | Colour | METALLIC PEARL WHITE | |
| | Odometer | 72729 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: STANDARD ALLOY RIM | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 185/60R15 | NEXEN | 7 | |
| | L/H Front Tyre | 185/60R15 | NEXEN | 7 | |
| | R/H Rear Tyre | 185/60R15 | NEXEN | 7 | |
| | L/H Rear Tyre | 185/60R15 | NEXEN | 7 | |
| 4. | Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | |
| J. | Accident Date | 23/09/2024 | Inspection Date | 02/10/2024 | |
| | Survey held at | ESTEEM PERFORMANCE PTE LTD | | | |
| | | 176 SIN MING DRIVE | | | |
| | | #01-14 SIN MING AUTOCARE SINGAPORE 575721 | | | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. | | | | | |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | | |