

SMU 1093K

Disposal call Kenneth
Before paint with old parts



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMU 1093 K

Parts	(a) Cost / List Price Items	\$ 10 893.80
	Plus/Less ^{25%} 10%	\$ 2 723.45
	Total of Cost / List	\$ 8 170.35
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	\$ 200
Total Parts Cost		\$ 8 370.35
Labour	\$	3,260.00
Total		\$ 11 630.35

Not authorized
Primary B4 paint
@ 5914.98

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth
Company : LICK
Survey conducted on : 21/10/24 at 11:00

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : De Date: 21/10/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SMU 1093 K
Make & Model : TOYOTA VIOS
Chassis No : MR2B23F3501203488

Submit By : JENNY
Year Manufacture : 29-Jul-20
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Bonnet <i>RL X</i>	1	\$1297.70		X
2	Bonnet lock <i>RL X</i>	1	\$182.00		X
3	Bonnet heat insulator <i>SL X</i>	1	\$329.20		X
4	Bonnet heat insulator clip <i>RL X</i>	10	\$60.00		X
5	Bonnet hinge LH <i>DIT</i>	1	\$81.80	81.80	2
6	Bonnet hinge RH <i>DIT</i>	1	\$81.80	81.80	2
7	Headlamp LH <i>81150-00F00 CMA</i>	1	\$1873.40	1873.40 ✓	✓
8	Front support panel (complete) <i>RL</i>	1	\$1532.50	<i>RL</i>	7
9	Front support top garnish <i>SL</i>	1	\$379.20		X
10	Front sensor <i>GR</i>	<i>41</i>	\$200.00	<i>S-N</i>	<i>41 100SN</i>
11	Front bumper <i>32119-00932 B/L CMA</i>	1	\$761.80	761.8 ✓	✓
12	Front bumper clip <i>RL</i>	10	\$60.00	60	✓
13	Front bumper reinforcement	1	\$615.60	<i>RL</i>	X
14	Front bumper side retainer LH <i>DIT</i>	1	\$153.50	153.50	✓
15	Front bumper side retainer RH <i>SL</i>	1	\$153.50		X
16	Front bumper bracket LH	1	\$353.70		X
17	Front bumper bracket RH	1	\$353.70		X
18	Front bumper sponge	1	N/A		X
19	Front bumper upper grille <i>SL</i>	1	\$99.00		X
20	Front bumper lower grille <i>53112-00540 CMA</i>	1	\$377.00	377 ✓	✓
21	Front bumper tow cover <i>3890 DIT</i>	1	\$126.10	126.1 ✓	✓
22	Fog lamp LH <i>MY CMA</i>	1	\$450.00	450	✓
23	LH front fender <i>53802-00100 B/L</i>	1	\$1162.50	1162.50 ✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SMU 1093 K**
 Make & Model : **TOYOTA VIOS**
 Chassis No : **MR2B23F3501203488**

Submit By : **JENNY**
 Year Manufacture : **44041**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
	53876-00661				
24	LH front fender undershield <i>CM</i>	1	<i>70.10</i>	<i>✓</i>	<i>2</i>
25	LH front fender undershield clip	10	<i>50.00</i>	<i>50</i>	<i>2</i>
26	RH front fender quarter garnish <i>21.5</i>	1	<i>57.20</i>	<i>57.20</i>	<i>✓</i>
27					
28					
29					
30	<i>supplement</i>				
31	<i>WFRM ✓</i>				
32	KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
33					
34					
35					
36					
37	Acknowledged by Repairer				
38	Signature:				
39	Date:				
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : SMU 1093 K Submit By : JENNY
Make & Model : TOYOTA VIOS Year of Manufacture : 44041

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (BONNET, FRONT BUMPER, SUPPORT PANEL, LHF FENDER, LHF DOOR)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (BONNET, FRONT BUMPER, SUPPORT PANEL, LHF FENDER, LHF DOOR)	\$1,200.00	600
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit radiator to assist work load. <i>nn</i>	\$150.00	X
			X
5	To remove & refit aircon condensor to assist work load, to top up A/C gas. <i>nn</i>	\$150.00	
6	To do wheel alignment.	\$120.00	60
7	To tuff coat.	\$150.00	30
8	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
9	To remove & refit front sensor	\$120.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any



WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

any of the quoted parts are recommended to be repaired, then an additional labour charge is charged accordingly under supplementary.