

ASS. REC. BY:

REF:

LAW/

CS/LAW24090482/Knp3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMU 1093K Yr Regn: 07, 20Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios C.C. 1498Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 72729 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2B 23F 3501203488Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal. 7 mm

Rear

R/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 23/9/24D.O.I. 2/10/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orR/L N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/10 @ 5914.98 (Red. \$ 5715.37, 497.)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

SL0M24900002 / Lai Huat (Meng Kee) Motor Pte Ltd
ENTRY DATE & TIME: 24/09/2024 11:08 (SGT)
SUBMITTED BY: LHMK -3
VERSION: 1 (24/09/2024 11:08 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	24/09/2024 11:08 (SGT)
Reported by	Owner
Date of Accident	23/09/2024 14:10 (SGT)
Exact Location of Accident	60 Airport Blvd., Singapore Changi Airport (SIN), Singapore 819643
Additional Location Information	Changi Airport Terminal 1, bay D30
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMU1093K
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Company Reg No	2XXXXX651D
Email Address	accident@gbcr.com.sg
Mobile Phone No	(Phone) +65-66039398
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1496
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	24-MAB00158-R00

Name of Driver	IMRAN BIN ALI
NRIC No	SXXXX811B
Date Of Birth	21/11/1988
Occupation	Outdoor
Driving Pass Date	18/12/2009
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	14 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97906174
Alt. Phone Number	-
Email Address	imran.ali@airbus.com
Address	BLK 109 RIVERVALE WALK #08-20
Address complement	-
Postcode	540109
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Authorised driver
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	GEORGE LIM
Gender	Male

PASSENGER 2

Name	SEE YAP YUONG
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	The video is with the owner.

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WD1376R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Mobile equipment
Name of Driver	ADAIKALARAJ JOHN EDISON
Contact Number	(Phone) +65-98791056
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

 23 SEPT 24 1800
Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card) **SOH JIT HOON**
Rec'd 24 SEP 2024

Sketch Plan



SKETCH PLAN #2

Describe Circumstance of the Accident

At approximately 1400 HRS, I (Imran Bin Ali DRIVER) along with 2 other passengers (George Lim (beside driver) and See Yap Yong (back seat) were heading towards Bay D36 SIAEC Airbus team office. We had just come from declaring the serviceability of 9V-SKM (SIA A380) which was parked at B2. (Departure SQ406)

Upon exiting the Terminal 1 Baggage handling area (speed limit of 15 KM/H), we made a left turn into Bay D30. For info, this area speed limit is 30 KM/H and car picked up speed.

After passing D30 bay at approximately 1410 HRS, a SATS tractor vehicle number WD1376R inched out of the remote stand and hit our car.

Pictures were taken and contacts were exchanged. No persons from both vehicles were injured.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Actual Driver's Signature (If driver is not the policyholder) / Date & Time

23 SEPT 2024

[Signature]

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

SOH JIT HOON
Rec'd 24 SEP 2024



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMU 1093 K

Parts	(a) Cost / List Price Items	_____
	Plus/Less 10%	_____
	Total of Cost / List	=====
	(b) Nett Price Items	_____
	Less	_____
	Total of Nett Item	=====
	(c) Special Nett Items	_____
Total Parts Cost		=====
Labour	\$	3,260.00
Total		=====

*Not authorized
Primary B4 paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 9% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 21/10/24 at 11:00

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De

Date: 21/10/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SMU 1093 K
Make & Model : TOYOTA VIOS
Chassis No : MR2B23F3501203488

Submit By : JENNY
Year Manufacture : 29-Jul-20
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Bonnet <i>RC X</i>	1			X
2	Bonnet lock <i>RC X</i>	1			X
3	Bonnet heat insulator <i>Sm X</i>	1			X
4	Bonnet heat insulator clip <i>nn X</i>	10			X
5	Bonnet hinge LH	1			?
6	Bonnet hinge RH	1			?
7	Headlamp LH <i>CPA</i>	1			
8	Front support panel (complete) <i>RC</i>	1			?
9	Front support top garnish <i>Sm</i>	1			X
10	Front sensor <i>Gr</i>	<i>4/1</i>			4
11	Front bumper <i>B4/1cm</i>	1			✓
12	Front bumper clip <i>nn</i>	10			✓
13	Front bumper reinforcement	1			?
14	Front bumper side retainer LH <i>Dr</i>	1			✓
15	Front bumper side retainer RH <i>Sm</i>	1			X
16	Front bumper bracket LH	1			?
17	Front bumper bracket RH	1			?
18	Front bumper sponge	1			?
19	Front bumper upper grille <i>Sm</i>	1			X
20	Front bumper lower grille <i>CPM</i>	1			✓
21	Front bumper tow cover <i>Dr</i>	1			✓
22	Fog lamp LH	1			?
23	LH front fender <i>Bu</i>	1			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SMU 1093 K

TOYOTA VIOS

MR2B23F3501203488

Submit By :

Year Manufacture :

Engine No. :

JENNY

44041

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH front fender undershield	1			?
25	LH front fender undershield clip	10			?
26	RH front fender quarter garnish <i>hit</i>	1			✓
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SMU 1093 K**
Make & Model : **TOYOTA VIOS**

Submit By : **JENNY**
Year of Manufacture : **44041**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF FENDER,LHF DOOR)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF FENDER,LHF DOOR)	\$1,200.00	600
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit radiator to assist work load. <i>nn</i>	\$150.00	X
5	To remove & refit aircon condensor to assist work load,to top up A/C gas. <i>nn</i>	\$150.00	X
6	To do wheel alignment.	\$120.00	60
7	To tuff coat.	\$150.00	30
8	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
9	To remove & refit front sensor	\$120.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any

SMU 1093K

Disposal call Kenneth
Before paint with old parts



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMU 1093 K

Parts (a) Cost / List Price Items

Plus/Less

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

Labour

Total

\$ 10 893.80

\$ 2728.45

\$ 8 170.35

\$ 200

\$ 8370.35

\$ 3,260.00

\$ 11 630.35

Not authorized
Primary B4 paint

\$ 5914.98

The above total will be subjected to 9% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Kenneth

CLICK

21/10/24

at 11:00

De

Date:

21/10/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SMU 1093 K
Make & Model : TOYOTA VIOS
Chassis No : MR2B23F3501203488

Submit By : JENNY
Year Manufacture : 29-Jul-20
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Bonnet <i>rx</i>	1	\$1297.70		X
2	Bonnet lock <i>rx</i>	1	\$188.00		X
3	Bonnet heat insulator <i>sn</i>	1	\$389.20		X
4	Bonnet heat insulator clip <i>nnx</i>	10	\$60.00		X
5	Bonnet hinge LH <i>dit</i>	1	\$218.20		2
6	Bonnet hinge RH <i>dit</i>	1	\$218.20		2
7	Headlamp LH <i>1393.40 cm</i>	1	\$173.40		✓
8	Front support panel (complete) <i>rx</i>	1	\$153.50	<i>rx</i>	7
9	Front support top garnish <i>sn</i>	1	\$379.20		X
10	Front sensor <i>cm</i>	1	\$200.00	<i>sn</i>	4 100sn
11	Front bumper <i>580.30 B1/cm</i>	1	\$761.20		✓
12	Front bumper clip <i>sn</i>	10	\$60.00		✓
13	Front bumper reinforcement	1	\$615.60	<i>rx</i>	X
14	Front bumper side retainer LH <i>dit</i>	1	\$153.50		✓
15	Front bumper side retainer RH <i>sn</i>	1	\$153.50		X
16	Front bumper bracket LH	1	\$353.70		X
17	Front bumper bracket RH	1	\$353.70		X
18	Front bumper sponge	1	N/A		X
19	Front bumper upper grille <i>sn</i>	1	\$99.00		X
20	Front bumper lower grille <i>2H cm</i>	1	\$377.00		✓
21	Front bumper tow cover <i>38.90 dit</i>	1	\$100.20		✓
22	Fog lamp LH <i>ny cm</i>	1	\$450.00		X
23	LH front fender <i>761. Bz</i>	1	\$1162.50		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SMU 1093 K
 Make & Model : TOYOTA VIOS
 Chassis No : MR2B23F3501203488

Submit By : JENNY
 Year Manufacture : 44041
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH front fender undershield 161 CM	1	\$70.10	✓	✓
25	LH front fender undershield clip	10	\$50.00		✓
26	RH front fender quarter garnish 215	1	\$57.20		✓
27					
28					
29					
30	Supplementary				
31	W/R Rim ✓				
32	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
33					
34					
35					
36					
37	Acknowledged by Repairer Signature: _____ Date: _____				
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200006485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : SMU 1093 K Submit By : JENNY
Make & Model : TOYOTA VIOS Year of Manufacture : 44041

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF FENDER,LHF DOOR)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF FENDER,LHF DOOR)	\$1,200.00	600
3	To check wiring, focus headlamp	\$50.00	200
4	To remove & refit radiator to assist work load. <i>nn</i>	\$150.00	X
5	To remove & refit aircon condensor to assist work load,to top up A/C gas. <i>nn</i>	\$150.00	X
6	To do wheel alignment.	\$120.00	600
7	To tuff coat.	\$150.00	300
8	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
9	To remove & refit front sensor	\$120.00	500

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any



WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Submit By : _____
 Year Manufacture : _____
 Engine No. : _____
Cost / List

[illegible]

any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.