

SMU 1093K

Disposal call Kenneth  
Before paint with old parts



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

**Repair Estimates**

SMU 1093 K

Parts (a) Cost / List Price Items

Plus/Less

25%  
10%

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

Labour

Total

\$ 10 893.80  
\$ 2723.45  
\$ 8170.35  
\$ 200  
\$ 8370.35  
\$ 3,260.00  
\$ 11 630.35

Not authorized  
Primary B4 paint  
@ 5914.98

The above total will be subjected to 9% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair

05

day(s)

(c) Resurvey

Required / Not Required

(d) Excess

:\$

(e) Signature of surveyor

De

Date:

2/10/24

Kenneth

CLKK

2/10/24

at

11:00

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive

Singapore 575718

(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive

Sin Ming Auto Care #01-14, #01-15, #01-16

Singapore 575721

(T) 6484 1221 (F) 6484 7829

**Spare Parts**

Vehicle No. : SMU 1093 K  
Make & Model : TOYOTA VIOS  
Chassis No : MR2B23F3501203488

Submit By : JENNY  
Year Manufacture : 29-Jul-20  
Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Bonnet <i>rc x</i>	1	\$1297.70		X
2	Bonnet lock <i>rc x</i>	1	\$188.00		X
3	Bonnet heat insulator <i>sn x</i>	1	\$379.20		X
4	Bonnet heat insulator clip <i>nn x</i>	10	\$60.00		X
<del>5</del>	Bonnet hinge LH <i>Dir</i>	1	\$81.20		<del>2</del>
<del>6</del>	Bonnet hinge RH <i>Dir</i>	1	\$81.20		<del>2</del>
<del>7</del>	Headlamp LH <i>1393.40 cm</i>	1	\$1873.40		✓
8	Front support panel (complete) <i>rc</i>	1	\$1532.50	<i>rc</i>	<del>7</del>
9	Front support top garnish <i>sn</i>	1	\$379.20		X
10	Front sensor <i>cr</i>	<del>1</del>	\$200.00	<i>sn</i>	<del>4</del> 1005N
<del>11</del>	Front bumper <i>580.30 B4/cm</i>	1	\$761.20		✓
12	Front bumper clip <i>sn</i>	10	\$60.00		✓
13	Front bumper reinforcement	1	\$615.60	<i>rc</i>	<del>X</del>
<del>14</del>	Front bumper side retainer LH <i>Dir</i>	1	\$153.50		✓
15	Front bumper side retainer RH <i>sn</i>	1	\$153.50		X
16	Front bumper bracket LH	1	\$353.70		X
17	Front bumper bracket RH	1	\$353.70		X
18	Front bumper sponge	1	N/A		X
<del>19</del>	Front bumper upper grille <i>sn</i>	1	\$99.00		X
<del>20</del>	Front bumper lower grille <i>288 cm</i>	1	\$377.00		✓
<del>21</del>	Front bumper tow cover <i>38.90 Dir</i>	1	\$100.20		✓
<del>22</del>	Fog lamp LH <i>ny cm</i>	1	\$450.00		✓
<del>23</del>	LH front fender <i>761. Bz</i>	1	\$1162.50		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**Spare Parts**

Vehicle No. : **SMU 1093 K**  
Make & Model : **TOYOTA VIOS**  
Chassis No : **MR2B23F3501203488**

Submit By : **JENNY**  
Year Manufacture : **44041**  
Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH front fender undershield 161 cm	1	₹10-10	✓	2
25	LH front fender undershield clip	10	₹50.00		2
26	RH front fender quarter garnish 215	1	₹57.20		✓
27					
28					
29					
30	Supplementary				
31	WFRM ✓				
32	<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul>Acknowledged by Repairer Signature: Date:</div>				
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Labour

Vehicle No. : SMU 1093 K  
Make & Model : TOYOTA VIOS

Submit By : JENNY  
Year of Manufacture : 44041

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF FENDER,LHF DOOR)	\$1,200.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF FENDER,LHF DOOR)	\$1,200.00	600
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit radiator to assist work load. <i>nn</i>	\$150.00	X
5	To remove & refit aircon condensor to assist work load, to top up A/C gas. <i>nn</i>	\$150.00	X
6	To do wheel alignment.	\$120.00	60
7	To tuff coat.	\$150.00	30
8	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
9	To remove & refit front sensor	\$120.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any





(T) 6484 1221 (F) 6484 7829

any of the quoted parts are recommended to be repaired, then an additional labour charge is charged accordingly under supplementary.