

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 16 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURAN	ICE PTE LTD	Ref:	CS/LIP24090483/Aqh3e2	
	ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	21/11/2024	
	SINGAPORE 04858	33	Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMU 6635P	Veh. Inspected	GBH 2996Y	
	Policy No.	-	Coverage	0	
	Claim No.	DVS24/0211	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	26/09/2024	
2.	2. Vehicle Details				
	Make & Model	ISUZU NHR87	C.C	1898	
	Engine No.	RZ4E10D136	Year of Reg.	13/04/2018	
	Chassis No.	JAANHR87EJ7100031	Colour	WHITE	
	Odometer	- KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195 R15C	YOKOHAMA	6	
	L/H Front Tyre	195 R15C	YOKOHAMA	6	
	R/H Rear Tyre	165 R13C	YOKOHAMA	6	
	L/H Rear Tyre	165 R13C	YOKOHAMA	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	23/09/2024	Inspection Date	26/09/2024	
	Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a.		Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair