

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24090488/Kqp3m4	
	(BUDGET DIRECT I	NSURANCE)	Date:	09/10/2024	
	190 CLEMENCEAU SINGAPORE SHOP	AVENUE #03-01 PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMY 5339E	Veh. Inspected	SMV 1007E	
	Policy No.	P10704720R02	Coverage	0	
	Claim No.	C10031906/CY	Excess	\$0.00	
	Assign From	CALEEN YIT	Assign Date	27/09/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA JAZZ 1.3 CVT	C.C	1318	
	Engine No.	L13B15000984	Year of Reg.	16/09/2020	
	Chassis No.	JHMGK3850LS218212	Colour	METALLIC RED	
	Odometer	27669 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	175/65R15	DUNLOP	9	
	L/H Front Tyre	175/65R15	DUNLOP	9	
	R/H Rear Tyre	175/65R15	DUNLOP	9	
	L/H Rear Tyre	175/65R15	DUNLOP	9	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	26/09/2024	Inspection Date	27/09/2024	
	Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair