



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
ATTN: ERIC WOO

INV No. AC2508477

INV Date 11/12/2025

Reference CD/LPC24090493/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBM 444K
Insured Veh. XE 5224C
Claim No. 24/24/24/VC05/029925
Policy No. Z24VC05026670
Accident Date 26/09/2024
Inspection Date 27/09/2024

Description	Total
Survey Inspection	400.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: ERIC WOO			Ref: CD/LPC24090493/Apa3q2(N) Date: 11/12/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 5224C	Veh. Inspected	GBM 444K
	Policy No.	Z24VC05026670	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/029925	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	27/09/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y00K210881	Colour	SILVER
	Odometer	200982 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	TRANSMATE	6 mm
	L/H Front Tyre	195 R15C	TRANSMATE	6 mm
	R/H Rear Tyre	155 R12C	DUNLOP	6 mm
	L/H Rear Tyre	155 R12C	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/09/2024	Inspection Date	27/09/2024
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBM 444K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DASHBOARD	NOT NECESSARY	1,870.20	-
1	FRONT BUMPER	DEFORMED	895.20	895.20
2	FRONT BUMPER FOGLAMP GARNISH L/R @ \$105.00	NOT NECESSARY	210.00	-
2	FRONT BUMPER INNER BRACKET L/R @ \$150.50	NOT NECESSARY	301.00	-
1	FRONT BUMPER INNER REINFORCEMENT	NOT NECESSARY	182.20	-
2	FRONT CORNER PANEL L/R @ \$336.40	N/S MISSING	672.80	336.40
2	FRONT DOOR INNER TRIM BOARD L/R @ \$629.30	NOT NECESSARY	1,258.60	-
2	FRONT DOOR L/R @ \$1794.20	DENTED	3,588.40	3,400.00
2	FRONT DOOR MECHANISM LOCK L/R @ \$404.40	NOT NECESSARY	808.80	-
1	FRONT GRILLE	NOT NECESSARY	595.20	-
1	FRONT GRILLE 'LOGO' EMBLEM	NOT NECESSARY	90.20	-
2	FRONT HEADLAMP L/R @ \$892.90	CRACKED	1,785.80	1,785.80
2	FRONT LH DOOR HINGES TOP AND BOTTOM @ \$144.50	NOT NECESSARY	289.00	-
1	FRONT LH DOOR INNER BRACKET	NOT NECESSARY	34.60	-
1	FRONT LH DOOR MOULDING	NECESSARY	78.70	78.70
1	FRONT LH DOOR SIDE GARNISH	CRACKED	57.30	57.30
1	FRONT LH DOOR WEATHER STRIP	NOT NECESSARY	246.50	-
1	FRONT LH SIDE MIRROR ASY	DAMAGED	986.20	986.20
1	FRONT LH SIDE MIRROR MOTOR	DAMAGED	756.40	756.40
1	FRONT LH SIDE MIRROR OUTER GARNISH	NOT NECESSARY	217.90	-
1	FRONT PANEL	NOT NECESSARY	1,194.30	-
1	FRONT PANEL 'DYNA' EMBLEM	NOT NECESSARY	89.90	-
1	FRONT RH STEP GARNISH	CUT	302.80	302.80
1	FRONT WINDSCREEN	CRACKED	2,199.40	1,510.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	327.60	327.60
1	FRONT WINDSCREEN RUBBER MOULDING	NOT NECESSARY	511.40	-
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	311.80	-
	LESS 25% DISCOUNT		-4,965.55	-2,609.10
			14,896.65	7,827.30

Report Ref No. CD/LPC24090493/Apa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
2	FRONT DOOR '3D' ART WORK STICKER @280.00 (SN)	NECESSARY	560.00	200.00
2	FRONT DOOR COMPANY STICKER DETAIL STICKER L/R @ \$25.00 (SN)	NECESSARY	50.00	50.00
2	FRONT DOOR INNER TRIM BOARD CLIPS L/R - SET @50.00 (SN)	NOT NECESSARY	100.00	-
1	FRONT GRILLE CLIPS - SET (SN)	NOT NECESSARY	50.00	-
2	FRONT HEADLAMP CLIPS L/R - SET @25.00 (SN)	NOT NECESSARY	50.00	-
			810.00	250.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)		80.00	30.00
	TO REMOVE, REINSTALL WINDSCREEN. (TO FR)		150.00	120.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.		180.00	120.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,800.00	1,000.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL.		1,600.00	1,000.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	40.00
			3,930.00	2,310.00
GRAND TOTAL			19,636.65	10,387.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,300.00

Report Ref No. CD/LPC24090493/Apa3q2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K





PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K




PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K




PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K



PHOTOGRAPHS FOR VEHICLE NO. : GBM 444K

