



CYCLE & CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SALINAH BEE D/O ABDUL LATIFF  761 Pasir Ris Street 71 #13-216 Singapore 510761  <b>Contact No</b> Mobile: 97903825	<b>Cust No/Name</b>	/SALINAH BEE D/O ABDUL LATIFF
	<b>Reg No/Reg Date</b>	SNG3341T / 27/07/2022
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	KNAF5416MN5122261
	<b>Engine No</b>	G4FGMH711574
	<b>Make/Model</b>	KIA/CERATO 1.6 A GT LINE H400 PE
	<b>Colour/Trim</b>	BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	18/09/2024/ 16:11		1015/ Vikneswaran Naidu A	11381

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, REPAIR RHS FENDER AND REPLACE DAMAGED PARTS				1600.00
E PNT98000 SPRAY FRT BUMPER, FRT RHS FENDER				1400.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00
A 10028901 CHECK WIRING AND ELECTRICAL				100.00
M SUNDRY SUPPLY PNL SEALANT				120.00
M SUNDRY SUNDRIES				80.00
E PNT88000 REMOVE AND REFIT SENSOR				80.00
M COVER-FR BUMPER	1.00	665.00	00.00	665.00
M GRILLE ASSY-RADIATOR	1.00	223.00	00.00	223.00
M GRILLE-FRONT BUMPER	1.00	362.00	00.00	362.00
M MOULDING ASSY-FRONT BUMPER,RH	1.00	194.00	00.00	194.00
M LAMP ASSY-FRONT FOG,RH	1.00	698.00	00.00	698.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	12.00	00.00	12.00
M LAMP ASSY-HEAD,RH	1.00	3342.00	00.00	3342.00

Estimate

Confirm & accepted by

	<b>Nett</b>	<b>9,156.00</b>
<b>9% GST on</b>	<b>9156.00</b>	<b>824.04</b>
	<b>Total Payable</b>	<b>9,980.04</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.