

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090502/UNP3M4**Date:** 23/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002459625
Claimant Vehicle No :	SNR7262D	Insured Vehicle No :	SMW8108X
Date of Loss:	25/09/2024	Nature of Claim:	TP
		Claim No:	374814

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNR7262D		
Make & Model:	TOYOTA LEXUS, 2.0 IS200T EXECUTIVE (A)	Engine No:	8ARZ082630
Reg. Date:	08/08/2017 (Man. Year: 2017)	Chassis No:	JTHBA1D2405056175
Colour:	White	Odometer:	124189 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 ZR19	Rear Tyre Size:	265/30 ZR19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,012.80	7,356.32	14,656.48	66.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	2,360.00	3,850.00	62.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,222.80	9,716.32	18,506.48	65.57
Approved Total (Overridden) (S\$)		7,700.00		
(S\$)	28,222.80	7,700.00	20,522.80	72.72
+ GST 9.00/9.00% (S\$)	2,540.05	693.00	1,847.05	72.72
Nett Amount (S\$)	30,762.85	8,393.00	22,369.85	72.72

INSPECTION

Date of Assignment:	27/09/2024	
Date Inspected:	27/09/2024	Inspected At: SPEEDWERKZ PTE LTD (AUTOBAY) (HQ) 1 KAKI BUKIT AVENUE 6 #01-73 SINGAPORE 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2024)
Parts:	143	TOYOTA LEXUS 2.0 IS200T EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNR7262D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Repair	2,738.70 FN	*- FN
2	1		*FRONT DOOR WINDOW OUTER GLASS MOULDING LH	Not Necessary	321.10 FN	*- FN
3	1		*REAR DOOR LH	Badly Dented	2,641.20 FN	*2,420.21 FN
4	1		*REAR DOOR WINDOW OUTER GLASS MOULDING LH	Not Necessary	321.10 FN	*- FN
5	1		*REAR DOOR OUTER HANDLE	Not Necessary	295.00 FN	*- FN
6	1		*REAR DOOR OUTER HANDLE SMALL COVER	Not Necessary	176.00 FN	*- FN
7	1		*REAR DOOR POWER WNDOW MOTOR AND REGULATOR LH	Bent/Damaged	825.10 FN	*825.10 FN
8	1		*REAR DOOR WEATHERSTRIPE LH	Not Necessary	286.00 FN	*- FN
9	2		*REAR DOOR HINGES LH	Serviceable	320.00 FN	*- FN
10	1		*REAR DOOR CHECKER LH	Not Necessary	178.00 FN	*- FN
11	1		*REAR DOOR LOCK LH	Damaged	512.00 FN	*512.00 FN
12	1		*REAR DOOR LOCK STRIKER LH	Not Necessary	98.00 FN	*- FN
13	1		*REAR DOOR INNER TRIMBOARD LH	Not Necessary	946.00 FN	*- FN
14	1		*REAR DOOR SPEAKER LH	Not Necessary	321.00 FN	*- FN
15	1		*ROCKER PANEL LH	Repair	863.00 FN	*- FN
16	1		*ROCKER PANEL GARNISH LH	Deformed/Torn	657.00 FN	*657.00 FN
17	1		*REAR WINDSCREEN MOULDING	Necessary	314.00 FN	*166.50 FN
18	1		*REAR FENDER LH	Badly Dented	2,689.80 FN	*2,421.32 FN
19	1		*REAR FENDER INNER SHIELD LH	Not Necessary	397.00 FN	*- FN
20	1		*REAR FENDER INNER TRIM LH	Not Necessary	1,021.00 FN	*- FN
21	1		*REAR SHOCK ABSORBER LH	Not Necessary	611.00 FN	*- FN
22	1		*REAR WHEEL HUB & BEARING LH	Damaged	516.00 FN	*516.00 FN
23	1		*REAR KNUCKLE ARM LH	Not Necessary	989.00 FN	*- FN
24	1		*REAR REAR UPPER CONTROL ARM FRONT LH	Not Necessary	345.00 FN	*- FN
25	1		*REAR UPPER CONTROL ARM LH	Not Necessary	496.00 FN	*- FN
26	1		*REAR LATERAL ARM FRONT LH	Not Necessary	318.00 FN	*- FN
27	1		*REAR LATERAL ARM LH	Not Necessary	446.00 FN	*- FN
28	1		*REAR LOWER CONTROL ARM LH	Not Necessary	438.00 FN	*- FN
29	1		*REAR STABILIZER LINK LH	Not Necessary	201.00 FN	*- FN
30	1		*REAR BUMPER	Not Necessary	1,422.00 FN	*- FN
31	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	189.00 FN	*- FN
32	1		*REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*20.00 FS
35	1		*REAR FENDER INNER TRIMBOARD LH CLIPS	Not Necessary	80.00 FS	*- FS
36	1		*REAR DOOR LH TRIMBOARD CLIPS	Not Necessary	80.00 FS	*- FS
37	1		*SET ROCKER PANEL GARNISH LH CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*REAR RIM LH	Cut	1,200.00 FS	*500.00 FS
39	1		*REAR RH TYRE	Serviceable	600.00 FS	*- FS
40	1		*FRONT DOOR LH TRIMBOARD CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	24,202.00	8,108.13
- Nett Item Discount on N Items 10.00/10.00% (S\$)	2,189.20	751.81
Total Parts (S\$)	22,012.80	7,356.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	0.00
3	TO REMOVE AND TRANSFER FRONT AND REAR DOOR RH FITTINGS TO NEW	New	300.00	60.00
4	TO REMOVE AND REPLACE REAR INTERIOR TRIMS AND GARNISH	New	180.00	60.00
5	TO REMOVE AND REFIT ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
6	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	150.00	120.00
7	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
8	TO REMOVE AND REPLACE REAR UNDERCARRIAGE COMPONENTS	New	350.00	120.00
9	TO REMOVE AND REPLACE REAR TYRE AND BALANCING	New	80.00	0.00
10	TO REMOVE AND REFIT PETROL TANK TO FACILITATE REPAIR	New	180.00	60.00
11	TO PROVIDE LABOUR,WORKMANSHIP	New	2,200.00	800.00
12	TO SPRAY PAINT ON AFFECTED PANELS - PEARL WHITE	New	1,800.00	1,000.00
13	RUST PROOFING	New	150.00	60.00
14	TO CONDUCT COMPUTERISE AND DIAGNOSTIC, TO RESET ECU AND REPROGRAMME	New	250.00	0.00
Gross Labour Cost (\$\$)			6,210.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >