

REF:

CS/SMR24090503/Anp3 (YQ 7132X)

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at Work m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remarks: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YQ7132X Yr Regn: 2022, June
 Type: M.Car / M.Cycle / Bus / Van / Loor / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino XZU710R C.D. 4089
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 71567 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JHHUCW2F90K043802

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/75R17.5
 R: 215/75R17.5

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 28/10/24

Survey held at IL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP 1st Cap.

COE Expiry: _____

Estimate given during: Yes (✓)
 1st Survey: No ()

MV: 108KPV: 27.2KNett: 80.8K

Adrian confirmed lump sum \$3300 and 5 days
 (red, \$20941.28, 86%)

415C

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair: 5

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

A. B. C. D. E. F. G. H. I. J. K. L. M. N. O. P. Q. R. S. T. U. V. W. X. Y. Z.

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 30.09.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEP
VEHICLE NO : **YQ7132X**
MODEL : **HINO XZU710R**
DATE OF ACCIDENT : 24.09.2024
TIME OF ACCIDENT : 16:12 HOURS

WE APPEND HEREUNDER THE ESTIMATED CC

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	CABIN ROOF TOP PANEL <i>Repr</i>	1	\$ 3,528.60	\$ 3,528.60
2	CABIN ROOF TOP INNER PANEL <i>Repr</i>	1	\$ 1,865.90	\$ 1,865.90
3	CABIN ROOF LINING <i>new</i>	1	\$ 1,355.90	\$ 1,355.90
4	FRONT WINDSCREEN GLASS <i>cracked</i>	1	\$ 1,865.20	\$ 1,865.20
5	FRONT WINDSCREEN GLASS MOULDING <i>new</i>	1	\$ 293.30	\$ 293.30
6	FRONT DOOR PILLAR LH <i>Repr</i>	1	\$ 1,836.20	\$ 1,836.20
7	FRONT DOOR PILLAR TOP LAMP LH <i>new</i>	1	\$ 238.50	\$ 238.50
8	FRONT DOOR PILLAR INNER TRIM LH <i>new</i>	1	\$ 395.60	\$ 395.60

TOTAL PRICE \$ 11,379.20
LESS 10% \$ 1,137.92
SUB TOTAL PRICE \$ 10,241.28

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	CABIN ROOF TOP PANEL SEALANT <i>new</i>	1	\$ 250.00	\$ 250.00
2	FRONT WINDSCREEN GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
3	FRONT WINDSCREEN GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00
4	FRONT WINDSCREEN GLASS SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00
5	REAR BOX FRONT PANEL (SPECAIL TYPE) <i>Detail</i>	1	\$ 2,500.00	\$ 2,500.00
6	REAR BOX SLIDING DOOR LH (SPECAIL TYPE) <i>new</i>	1	\$ 4,800.00	\$ 4,800.00
7	REAR BOX DOOR PILLAR COVER LH (SPECAIL TYPE) <i>new</i>	1	\$ 800.00	\$ 800.00

TOTAL \$ 9,040.00

TO : **MS FIRST CAP** MOTOR CLAIMS DEP
VEHICLE NO : **YQ7132X**
MODEL : **HINO XZU710R**
DATE OF ACCIDENT : 24.09.2024
TIME OF ACCIDENT : 16:12 HOURS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,600.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	300
3	TO SPRAY TUFF COAT	\$ 250.00	40
4	WIRING, BULB CHECKING	\$ 80.00	x
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	x
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	x
7	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,960.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,281.28
TOTAL LABOUR COST : \$ 4,960.00
TOTAL REPAIR COST : \$ 24,241.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Cj
A/s 28/10/24

05 Days