



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS3/SPF24090505/Eqp3m4	
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)		Date:	09/10/2024	
POLICE LOGISTICS BASE (PLB)		Code:	SPF	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	TP 468M	Veh. Inspected	FBH 4787X	
Policy No.	-	Coverage	0	
Claim No.	ACS/105/009/2024/051(CF)	Excess	\$0.00	
Assign From	LAI PENGCHONG	Assign Date	27/09/2024	
2. Vehicle Details				
Make & Model	HONDA CB400	C.C	399	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JH2NC4291BK300435	Colour	WHITE	
Odometer	- KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	120/60ZR17	PIRELLI	5	
L/H Front Tyre				
R/H Rear Tyre	160/60ZR17	PIRELLI	5	
L/H Rear Tyre				
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2024	Inspection Date	27/09/2024 (15:11)	
Survey held at	TRAFFIC POLICE VEHICLE POUND 517 AIRPORT BOULEVARD S(539942)			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				