

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|-----------------------------------|-----------------|------------------------|--|
| MS | AUTOMOTIVE ENGR | RG. & MGT. DIVISION (TP) | Ref: | CS3/SPF24090505/Eqp3m4 | |
| | ACCIDENT CLAIMS | ` , | Date: | 09/10/2024 | |
| | (SPORE POLICE FO | | Date. | 03/10/2024 | |
| | POLICE LOGISTICS | | Code: | SPF | |
| <u> </u> | 1 HEMMANT ROAD SINGAPORE 438675 | | | | |
| 1. | · | | | | |
| | | 1P 408IVI | Veh. Inspected | FBH 4787X | |
| | Policy No. | - A CO (405 (000 (000 4 (054 (05) | Coverage | 0 | |
| | Claim No. | ACS/105/009/2024/051(CF) | Excess | \$0.00 | |
| _ | Assign From | LAI PENGCHONG | Assign Date | 27/09/2024 | |
| 2. | 2. Vehicle Details | | | | |
| | Make & Model | HONDA CB400 | C.C | 399 | |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | JH2NC4291BK300435 | Colour | WHITE | |
| | Odometer | - KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | FAIR | |
| | Modification(s) | RIMS: SPORTS RIM | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 120/60ZR17 | PIRELLI | 5 | |
| | L/H Front Tyre | | | | |
| | R/H Rear Tyre | 160/60ZR17 | PIRELLI | 5 | |
| | L/H Rear Tyre | | | | |
| 4. | . Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. General Information | | | | | |
| J. | Accident Date | 22/09/2024 | Inspection Date | 27/09/2024 (15:11) | |
| | Survey held at | TRAFFIC POLICE VEHICLE POUN | | | |
| 5a. | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. | | | | | |
| B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. | | | | | |
| THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. | | | | | |
| C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | |
| 5b. Estimate Days of Repair | | | | | |
| EST | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | |