1/17/25, 11:24 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090507/UMA3Q2

Date: 17/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0001862_03

Claimant Vehicle SLJ5921P Insured Vehicle No: SNB2395X

No:

Date of Loss: 22/08/2024 Nature of Claim: TP Claim No: MFL2024D0009900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ5921P**

HONDA ODYSSEY, 2.4 EXV-S CVT SR (A) Make & Model: Engine No: K24W72013101 Reg. Date: Chassis No: JHMRC1890GC207122 16/12/2016 (Man. Year: 2016)

Colour: Silver Odometer: 131154 km

Engine Capacity: 2356 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	961.52	856.80	104.72	10.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	630.00	850.00	57.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	2,441.52	1,486.80	954.72	39.10
Approved Total (Overridden) (S	5)	1,150.00		
(5\$	2,441.52	1,150.00	1,291.52	52.90
+ GST 9.00/9.00% (S\$	219.74	103.50	116.24	52.90
Nett Amount (S\$	2,661.26	1,253.50	1,407.76	52.90
+ Loss of Use (2.0	x S\$100.00/day) (S\$)	200.00		
	Nett Liability (S\$)	1,453.50		
Global	Sum Settlement (S\$)	1,450.00		

INSPECTION

Date Inspected:

Date of Assignment: 04/10/2024

Hock Wah Motor Workshop Pte Ltd - bedok (HQ)

Blk 3011 Bedok North Avenue 4, #01-

2008/2010/2012/2014

Singapore 489977

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

04/10/2024 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2024)

Parts: M1-SUV HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ5921P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented / Bent	1,071.00 FL	*1,071.00 FL
2	1		*REAR DOOR INNER RUBBER LH	Not Necessary	130.90 FL	*-FL
3	1		*FRONT DOOR LH (NPA)	Repair	0.00 FS	*-FS
F=Fra	ınchise	part. S=SpcNe	tt. L=ListItemDisc.	_		
				Sub Total (S\$)	1,201.90	1,071.00
			- List Item Discount o	n L Items 20.00/20.00% (S\$)	240.38	214.20
				Total Parts (S\$)	961.52	856.80
			Report was unsubmitted	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount						
Lab	<u>Labour Items</u>									
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	200.00						
2	SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	400.00						
3	ANTI RUST COATING	New	80.00	30.00						
		Gross Labour Cost (S\$)	1,480.00	630.00						
	Report was unsubmitted during this print-out.									

< END OF ESTIMATES >