



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2501024

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/02/2025
Reference CD/CTI24090510/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 5290L
Insured Veh. SMR 2815D
Claim No. SNM24D205342
Policy No. DMPCSNW00034822400
Accident Date 22/09/2024
Inspection Date 30/09/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,

Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

Affiliated to Federation Internationale Des Experts En Automobile				
MS CHINA TAIPING INSURANCE (S) PTE LTD		Ref:		CD/CTI24090510/Kpa3q2
3 ANSON ROAD #16-00		Date:		19/02/2025
SPRINGLEAF TOWER SINGAPORE 079909		Code:		CTI
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SMR 2815D	Veh. Inspected	SMA 5290L	
Policy No.	DMPCSNW00034822400	Coverage	0	
Claim No.	SNM24D205342	Excess	\$0.00	
Assign From	LYNN KHONG	Assign Date	30/09/2024	
2. Vehicle Details				
Make & Model	KIA CARENS 1.7 DCT DIESEL 5DR FWD	C.C	1685	
Engine No.	D4FDJH552914	Year of Reg.	12/06/2018	
Chassis No.	KNAHU815VJ7208157	Colour	RED	
Odometer	142419 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	205/55R16	YOKOHAMA	9	
L/H Front Tyre	205/55R16	YOKOHAMA	9	
R/H Rear Tyre	205/55R16	YOKOHAMA	9	
L/H Rear Tyre	205/55R16	YOKOHAMA	9	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2024	Inspection Date	30/09/2024	
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMA 5290L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	CRACKED	\$750.00	\$698.60
1	REAR BUMPER LOWER	CRACKED	\$200.00	\$200.00
1	REAR BUMPER LOWER OUTER MOULDING	DENTED	\$190.00	\$190.00
1	REAR BUMPER TOWING COVER	DENTED	\$10.00	\$10.00
1	REAR LH FOG LAMP	CRACKED	\$180.00	\$125.90
2	REAR REVERSE SENSOR @\$160.00	DENTED	\$320.00	\$320.00
1	SMART KEY ANTENNA	DENTED	\$120.00	\$120.00
1	REAR BUMPER REINFORCEMENT	BENT	\$350.00	\$350.00
1	REAR LH BUMPER REINFORCEMENT BRACKET	BENT	\$150.00	\$150.00
1	REAR RH BUMPER REINFORCEMENT BRACKET	BENT	\$150.00	\$150.00
1	REAR BOOT	BENT	\$1,300.00	\$1,300.00
1	REAR BOOT KIA LOGO	NOT NECESSARY	\$100.00	\$0.00
1	REAR BOOT CARENS EMBLEM	NECESSARY	\$80.00	\$80.00
1	REAR BOOT CRDI EMBLEM	NECESSARY	\$40.00	\$40.00
1	REAR BOOT WEATHERSTRIP	DISTORTED / DENTED	\$140.00	\$140.00
1	REAR BOOT LOCK	DENTED	\$150.00	\$150.00
1	REAR BOOT CENTER CHROME MOULDING	SERVICEABLE	\$180.00	\$0.00
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	\$280.00	\$0.00
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	\$280.00	\$0.00
1	TAILLAMP RH	SERVICEABLE	\$320.00	\$0.00
1	REAR BOOT INNER TRIM BOARD	MTG CRACKED	\$280.00	\$280.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$800.00	\$0.00
1	REAR END PANEL TRIM BOARD	MTG DISTORTED	\$90.00	\$90.00
1	FRONT BUMPER	BUCKLED	\$650.00	\$650.00
1	FRONT BUMPER KIA LOGO	NECESSARY	\$100.00	\$100.00
1	RADIATOR GRILLE	MTG CRACKED	\$450.00	\$450.00
1	FRONT BUMPER ENERGY ABSORBER	CRACKED	\$90.00	\$90.00
1	FRONT BUMPER REINFORCEMENT	BUCKLED	\$360.00	\$360.00
1	FRONT BUMPER SKID PLATE	SERVICEABLE	\$200.00	\$0.00
1	FRONT LH BUMPER FOG LAMP COVER	SERVICEABLE	\$130.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH BUMPER RETAINER	SERVICEABLE	\$20.00	\$0.00
1	FRONT RH BUMPER SIDE SUPPORT BRACKET	CRACKED	\$30.00	\$30.00
1	FRONT RH HEADLAMP	MTG CRACKED	\$1,800.00	\$1,692.50
1	FRONT RADIATOR SUPPORT PANEL	SERVICEABLE	\$750.00	\$0.00
1	FRONT LH FENDER PANEL (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	FRONT RH FENDER PANEL (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	FRONT BONNET (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	REAR BOOT OUTER GARNISH (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 10.00% DISCOUNT		(\$1,104.00)	(\$776.70)
			\$9,936.00	\$6,990.30

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	FRONT FENDER LINER CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	\$120.00	\$0.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	\$150.00	\$30.00
1	REAR BUMPER LOWER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR BOOT INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$120.00	\$40.00
1	REAR WINDSCREEN PRIMER (SN)	NECESSARY	\$100.00	\$30.00
1	REAR WINDSCREEN MOULDING (SN)	NOT NECESSARY	\$150.00	\$0.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	\$100.00	\$0.00
1	REAR BOOT OUTER GARNISH CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	TAILLAMP GUIDE CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR END PANEL TRIM BOARD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	FRONT LICENCE PLATE NUMBER WITH FRAME (SN)	BENT	\$55.00	\$45.00
1	REAR LICENCE PLATE NUMBER WITH FRAME (SN)	SERVICEABLE	\$55.00	\$0.00
			\$1,250.00	\$295.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE ,REPLACE REFIX REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC		\$1,500.00	\$700.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT ,REAR BUMPER ,REAR END PANEL,FRONT BUMPER ,FRONT LH & RH FENDER FRONT BONNET ,ETC		\$1,800.00	\$800.00
	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC		\$150.00	\$120.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS		\$120.00	\$60.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC		\$100.00	\$60.00
	TO TUFF KOTE & UNDERSEAL MATERIALS		\$150.00	\$30.00
	TO REMOVE AND REFIT A/C CONDENSER ,RADIATOR AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	NOT NECESSARY	\$220.00	\$0.00
	TO VACUUM AND TOPUP A/C GAS	NOT NECESSARY	\$150.00	\$0.00
	TO CHECK WIRING & ELECTRICAL SYSTEM		\$100.00	\$40.00
	TO READJUST AND REALIGN HEADLAMP AIM	NOT NECESSARY	\$100.00	\$0.00
	TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS LININGS COVER ,GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR		\$300.00	\$50.00
			\$4,690.00	\$1,860.00
GRAND TOTAL			\$15,876.00	\$9,145.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$7,300.00
Report Ref No: CD/CTI24090510/Kpa3q2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L



PHOTOGRAPHS FOR VEHICLE NO. : SMA 5290L

