



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2445C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT FENDER | TO REPAIR SEE LABOUR | 898.00 | - |
| 1 | FRONT DOOR | DENTED | 1,462.00 | 1,462.00 |
| 1 | FRONT DOOR LOCK | NOT NECESSARY | 289.00 | - |
| 1 | FRONT DOOR WEATHERSTRIPE | NECESSARY | 205.00 | 205.00 |
| 1 | FRONT DOOR GLASS | CUT | 495.00 | 495.00 |
| 1 | FRONT DOOR GLASS OUTER MOULDING | DENTED | 181.00 | 181.00 |
| 1 | FRONT DOOR WING MIRROR | DAMAGED | 1,185.00 | 1,085.00 |
| 1 | FRONT DOOR OUTER HANDLE | NOT NECESSARY | 286.00 | - |
| 1 | REAR DOOR | DENTED | 1,510.00 | 1,410.00 |
| 1 | REAR DOOR LOCK | NOT NECESSARY | 299.00 | - |
| 1 | REAR DOOR WEATHERSTRIPE | NOT NECESSARY | 219.00 | - |
| 1 | ROCKER PANEL OUTER SKIRTING | DEFORMED | 855.00 | 855.00 |
| 2 | ROCKER PANEL OUTER SKIRTING BRACKET @\$65.00 | NOT NECESSARY | 130.00 | - |
| | LESS 5% DISCOUNT | | -400.70 | - |
| | LESS 10% DISCOUNT | | - | -569.30 |
| | | | 7,613.30 | 5,123.70 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET ROCKER PANEL OUTER SKIRTING CLIPS (SN) | NECESSARY | 30.00 | 30.00 |
| | | | 30.00 | 30.00 |
| <u>LABOUR</u> | | | | |
| | PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER. | | 1,000.00 | 400.00 |
| | SPRAY PAINTING TO AFFECTED AREA. | | 1,000.00 | 600.00 |
| | WIRING CHECK. | | 50.00 | 30.00 |
| | TO SPRAY TUFF COAT. | NOT NECESSARY | 150.00 | - |
| | TO TRANSFER FRONT & REAR DOOR FITTINGS. | | 300.00 | 120.00 |
| | | | 2,500.00 | 1,150.00 |
| GRAND TOTAL | | | 10,143.30 | 6,303.70 |



| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | 5,000.00 |
|---|--|--|-----------------|

Report Ref No. CS/INC24090511/Aqh3e2

TOTAL FOR SPARE PARTS: \$ 7,643.30 \$ 5,153.70
TOTAL FOR LABOUR : \$ 2,500.00 \$ 1,150.00
TOTAL REPAIR COST: \$ 10,143.30 \$ 6,303.70

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.