



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 4830K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILLAMP RH	NOT NECESSARY	\$815.00	\$0.00
2	TAILLAMP PANEL @\$398.00	NOT NECESSARY	\$796.00	\$0.00
2	REAR FENDER @\$1024.00	TO REPAIR SEE LABOUR	\$2,048.00	\$0.00
1	REAR FENDER BLINDSPORT SENSOR	NOT NECESSARY	\$1,124.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$695.00	\$0.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	\$280.00	\$0.00
1	REAR BUMPER	DENTED	\$1,025.00	\$798.00
1	REAR BUMPER SIDE RETAINER RH	BROKEN	\$112.00	\$112.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	\$68.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,740.75)	(\$227.50)
			\$5,222.25	\$682.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	REAR BUMPER CLIPS @\$6.50 (SN)	NECESSARY	\$65.00	\$30.00
1	BOOTLID STICKER (SN)	NOT NECESSARY	\$100.00	\$0.00
4	TAILLAMP CLIPS @\$8.00 (SN)	NOT NECESSARY	\$32.00	\$0.00
6	REAR END PANEL TOP GARNISH CLIPS @\$6.50 (SN)	NOT NECESSARY	\$39.00	\$0.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	\$220.00	\$0.00
			\$456.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER AND REAR END PANEL		\$800.00	\$300.00
	TO SPRAY PAINT AFFECTED AREA		\$800.00	\$300.00
	TUFF COAT		\$250.00	\$20.00
	WIRING CHECK		\$80.00	\$30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	NOT NECESSARY	\$300.00	\$0.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$80.00	\$30.00
			\$2,310.00	\$680.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$7,988.25	\$1,392.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,100.00
Report Ref No: CS/FCI24090512/Evp3e2			

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.