

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090513/AUA3Q2
Date: 19/06/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0002376_04
Claimant Vehicle No : SDS448U Insured Vehicle No : YN4831Y
Date of Loss: 16/09/2024 Nature of Claim: TP Claim No: MFL2024D0011107

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDS448U
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Engine No: G4FGJU233247
Reg. Date: 27/07/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU726470
Colour: Silver Odometer: 33243 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,338.80	3,116.32	4,222.48	57.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	830.00	3,730.00	81.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,898.80	3,946.32	7,952.48	66.83
Approved Total (Overridden) (S\$)		3,150.00		
(S\$)	11,898.80	3,150.00	8,748.80	73.53
+ GST 9.00/9.00% (S\$)	1,070.89	283.50	787.39	73.53
Nett Amount (S\$)	12,969.69	3,433.50	9,536.19	73.53
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		3,704.50		
Global Sum Settlement (S\$)		3,700.00		

INSPECTION

Date of Assignment: 30/09/2024
Date Inspected: 30/09/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2025)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS448U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	798.40 FL	*474.00 FL
2	1		*FRONT BUMPER FOGLAMP C/W BRACKET RH	Not Necessary	294.70 FL	*- FL
3	1		*FRONT BUMPER FOGLAMP COVER GARNISH RH	Not Necessary	121.30 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	93.60 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	217.60 FL	*- FL
6	2		*FRONT BUMPER SIDE BEAM	Not Necessary	195.80 FL	*- FL
7	1		*FRONT BUMPER TOP RUBBER	Not Necessary	69.40 FL	*- FL
8	1		*BONNET	Dented	1,385.00 FL	*1,385.00 FL
9	1		*BONNET LOCK	Not Necessary	129.90 FL	*- FL
10	2		*BONNET HINGE	Not Necessary	98.20 FL	*- FL
11	1		*BONNET INSULATOR	Not Necessary	221.10 FL	*- FL
12	4		*BONNET STOPPER	Not Necessary	72.40 FL	*- FL
13	1		*HRAD LAMP RH	Cracked	1,198.80 FL	*1,198.80 FL
14	1		*HRAD LAMP LOWER BRACKET	O/S Cracked	179.20 FL	*89.60 FL
15	4		*HEADLAMP CLIP	Not Necessary	106.80 FL	*- FL
16	2		*HEADLAMP BOTTOM SUPPORT BRACKET	Not Necessary	55.20 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Not Necessary	949.30 FL	*- FL
18	1		*FRONT FENDER RH	Distorted	730.00 FL	*495.00 FL
19	1		*FRONT FENDER MUDFLAP RH	Not Necessary	165.00 FL	*- FL
20	1		*FRONT FENDER COWLING RH	Torn	178.00 FL	*178.00 FL
21	1		*FRONT DOOR VIEW MIRROR RH	Not Necessary	1,248.60 FL	*- FL
22	1		*FRONT FENDER TOP CORNER GARNISH RH	Not Necessary	38.60 FL	*- FL
23	1		*FRONT FENDER TOP INNER GARNISH RH	Not Necessary	164.10 FL	*- FL
24	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
25	1		*SET CENTER GRILLE CLIP	Not Necessary	50.00 FS	*- FS
26	1		*BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
27	1		*SET FRONT FENDER INNER COWLIN CLIP	Necessary	50.00 FS	*30.00 FS
28	1		*SET FRONT SUPPORT PANEL TOP COVER GARNISH	Not Necessary	30.00 FS	*- FS
29	1		*SET FRONT ENGINE UNDER COVER CLIP	Not Necessary	50.00 FS	*- FS
30	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,081.00	3,880.40
- List Item Discount on L Items 20.00/20.00% (S\$)	1,742.20	764.08
Total Parts (S\$)	7,338.80	3,116.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	400.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	250.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	REMOVE AND REFIX DASH BOARD AND INTERNAL WIRING	New	850.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			4,560.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >