NCVI INVOLVING 6TON (21812MID) AND SBS BUS (SMB3161J) ALONG SEMBAWANG ROAD ON 27 SEP 2024 AT AROUND 1140H

OFFICIAL (CLOSED) \setminus SENSITIVE NORMAL



Figure A-1: Overview of Incident Site




Figure A-2: Overview of Incident Site

Schematic Diagram of Incident



IVC TIMESTAMP: 03:29:16




BUS (SMB3161J) Turned on hazard light, Signalling to Stop. Car behind slowing down to a halt.

Figure A-3

Schematic Diagram of Incident






BUS (SMB3161J) Starts moving into bus stop lane.

Figure A-4

Schematic Diagram of Incident



IVC TIMESTAMP: 03:29:18



BUS (SMB3161J) Starts moving into bus stop lane.

Figure A-5



Figure A-6





Figure A-7

Schematic Diagram of Incident



IVC TIMESTAMP: 03:29:21




White Car Infront is clear and proceeds past the BUS (SMB3161J).

Figure A-8

Schematic Diagram of Incident






White Car Infront drives past the BUS (SMB3161J) .

Figure A-9

Schematic Diagram of Incident





6TON (MID21812) Drives forward towards BUS (SMB3161J)

Figure A-10





Figure A-11

Schematic Diagram of Incident



IVC TIMESTAMP: 03:29:25




6TON (MID21812) Drives forward towards BUS (SMB3161J)

Figure A-12

Schematic Diagram of Incident



IVC TIMESTAMP: 03:29:26



6TON (MID21812) Hits and grazes BUS (SMB3161J)

Figure A-13



Figure B-1: Front View of MID21812



Figure B-2: Rear View of MID21812



Figure B-3: Left Side View of Mid21812



Figure B-4: Right Side View of MID21812



Figure B-5: Close-up View of Damages to MID21812



Figure B-6: Close-up View of Damages to MID21812



Figure B-7: Close-up View of Damages to MID21812



Figure B-8: Close-up View of Damages to MID21812



Figure B-9: Close-up View of Damages to MID21812



Figure B-10: Close-up View of Damages to MID21812

Damage Assessment: MID 21812 sustained the following damages:

- 1. Torn Canopy
- 2. Scratches along left hand side
- 3. Torn spare wheel cover
- 4. Dented toolbox
- 5. Broken side light
- 6. Broken left side-view mirror
- 7. Cracked front-left mudguard



Figure B-11: Close-up View of Damages to SMB2161J



Figure B-12: Close-up View of Damages to SMB2161J



Figure B-13: Close-up View of Damages to SMB2161J

Damage Assessment: SMB2161J sustained the following damages:

- 1. Broken right tail light
- 2. Shattered rear window pane
- 3. Broken Rear Camera
- 4. Shattered rear right window pane shattered

SINGAPORE ARMED FORCES STATEMENT OF DRIVER/WITNESS

STATEMEN	NT OF	ee ri	4.				ALIASE	S		
NRIC NO		753 G	AGE		18		MALE/	FEMALE	male	
EMPLOYME	ENT		DRIVIN	E NO	SAFAET	Javanitted.	NATIO	NALITY	Maley	49
DIALECT			LANGU		man	darin	TEL NO			
ADDRESS			-							
INTERPRET	ED BY		RANK		TIME		DATE	1	SIGN	180
RECORDED	BY EZE	KITEL CHUA	RANK	2LT	TIME	1504	DATE	270424	SIGN	24
the 6	-Ton for Gedona (I Saw	pop Cp	3SG Soleter Soleter	Con	timat	Mah Zho Draina H	gramy	1.10	n dri. Iroue f Sembal	rom
side p safely did no	metroding manes	a bus and outward whide con a to slow a collide	mande dov	they to	of the	to stop.	200000000000000000000000000000000000000	drie on but	the 6	el_

All statements and further statements are to be timed and dated, Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.

Statements of witness must be signed by the witness.

Figure C-1: Statement of TO

SINGAPORE ARMED FORCES STATEMENT OF DRIVER/WITNESS

A STATE OF THE PARTY OF THE PAR	T OF	Mayer Mah	Zhen Qiv	4	ALIASES	
NRIC NO		1918	AGE	22	MALE/FEMALE	Male
EMPLOYMEN	NT		DRIVING LICENCE NO	SAF /111 / H /00441/24	NATIONALITY	Singaporean
DIALECT		Hainanese	LANGUAGE SPOKEN	-	TEL NO	
ADDRESS						
NTERPRETE	D BY		RANK	TIME	DATE	SIGN
RECORDED	BY	EZEWEL CHUA	RANK 2LT	TIME 1804	DATE 270124	SIGN AZ
here mi training Road, bus st of the	aving Correction	off from si we's Continua tonner was 57029: Afti is protrudin	ungei Ged tion Progra behind t the Spa g outwo	- · ·	the drive a ovs entered ired that t I saw that	y for DCP of Sembawang into the he rear right our torner's
Slow	down	driver to s	slow do	wn. The torne G-Ton's left of the bus.	r did not n Side mirro	nanage to

SAF 1201/91

All statements and further statements are to be timed and dated, Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.

Statements of witness must be signed by the witness.

Figure C-2: Statement of VC




Figure D-1

OFFICIAL (CLOSED) STAFF-IN-CONFIDENCE

ANNEX H





Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. 7/20240927/7051

Driver					
Name	LEE ZI QI		ID No.		753G
Related Vehicle	NIL	*	Conta	ot No.	
Hospital/Clinic	NIL		Class Driving Licens Expiry	e &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	arge	NIL	
No. of Days grant	ed Medical Leave (MC) NIL	Degree of	njury	NIL	
Passenger					
Name	MAYER MAH ZHEN QIU		ID No.		191B
Related Vehicle	NIL		Conta	ot No.	
Hospital/Clinic	NIL		Class Driving Licence Expiry	e &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	arge	NIL	-
No. of Days grant	ed Medical Leave (MC) NIL	Degree of	njury	NIL	

Brief Details.

The 6-Ton left side mirror collided against the right rear side of the bus, this happened at bus-stop 57029, along Sembawang Road.

Figure D-2

POLICE FORCE Police Station Of Origin:	T/20240927/7051
Fraffic Police 0 Ubi Avenue 3 SINGAPORE 408865 Fel No: 65470000	Report No. T/20240927/70 CONTINUATION OF REPORT
Signature Of Officer Recording The Report. Not applicable	Signature Of Informant: The identity of the person making this report has be authenticated by Singpass. No signature is required
Signature Of Officer Recording The Report. Not applicable Signature Of Interpreter: Not applicable	Signature Of Informant: The identity of the person making this report has be authenticated by Singpass. No signature is required Date/Time: 27/09/2024 14:30

Figure D-3