

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090516/RPA3Q2
Date: 07/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0008927_02
Claimant Vehicle No : GBJ7930T Insured Vehicle No : SLR2512P
Date of Loss: 14/09/2024 Nature of Claim: TP Claim No: MFL2024D0011592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ7930T
Make & Model: NISSAN NV200, 1.5 MT (M) Engine No: K9KE628D701973
Reg. Date: 28/08/2019 (Man. Year: 2019) Chassis No: VSKYBAM20Z0179677
Colour: White Odometer: 94212 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14C Rear Tyre Size: 175/70 R14C
Front Left Side: Comforest 6 mm Rear Left Side: Comforest 6 mm
Front Right Side: Comforest 6 mm Rear Right Side: Comforest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	382.68	0.00	382.68	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	450.00	580.00	56.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,412.68	450.00	962.68	68.15
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/09/2024
Date Inspected: 30/09/2024 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Mar 2025)	
Parts:	N/A	NISSAN NV200 1.5 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ7930T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (NPA)	Not Necessary	0.00 FN	*- FN
2	1		*HEADLAMP LH	Not Necessary	425.20 FN	*- FN
3	1		*HEADLAMP LOWER PANEL GARNISH LH (NPA)	Not Necessary	0.00 FN	*- FN
F=Franchise part. N=NettItemDisc.						
Sub Total (S\$)					425.20	0.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)					42.52	0.00
Total Parts (S\$)					382.68	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	500.00	150.00
2	TO RESPRAY AFFECTED AREAS	New	500.00	300.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	0.00
Gross Labour Cost (\$\$)			1,030.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >