

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

3rd Oct 2024

Lonpac Insurance Bhd 300 Beach Road, The Concourse, #17-04/06, Singapore 199555

To who it may concern,

Accident between FBT9863M & XD9447E on 3 Sep 24

I am writing to inform you that, following a thorough assessment, our client's vehicle has been deemed beyond economic repair. The damage sustained from the accident has resulted in extensive costs that exceed the vehicle's current market value.

Therefore, we have decided not to proceed with repairs.

Thanks.

A.

Regards Stephanie Gan

Insurance Manager

NO + Authoral 30/9/24 70/AL 1085 LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:







MOTORCYCLE ACCESSORIES | SERVICE CENTRE MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Customer:

LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702

ATTN: LONPAC INSURANCE BHD

QUOTATION

NO.: 47817

30/09/24

d/S= DATE: 30/09/2024

CLAIM NO.: 12603

POLICY NO.: MC/01230958/01

7 ans? FROM: STEPLIANCE

VEHICLE NO.

: FBT9863M

MAKE/MODEL

: K.T.M / 1290 SUPER ADVE

(Page 1 of 7)

S/N	Description	Action	Qty	Unit Price	Amount
1	AIR DUCT INTAKE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	CM 94.00
2	AIR INTAKE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00-
3	AXLE FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	280.00
4	BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$1,550.00	1,550.00
5	BOLT M5X14 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$7.00	ru 14.00
6	BOLT STEERING HEAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	NM 71.00
7	BRACKET FUEL HOSE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
8	BRACKET UNDER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,085.00	cre/1,085.00
9	BRAKE FLUID DOT5.1 0,25L P/N: 63833 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00







Quota	ation Nos. : 47817				(Page	e 2 of 7)
6/N	Description	Action	Qty	Unit Price		<u>Amount</u>
0	CAMERA (V_SYS) M6 (WIFI VERSION) P/N: 56377	REPLACE	1.00	\$388.00	?	388.00
	- (REPORTED BY MECHANIC)				_	
1	CLIP EXHAUST 60MM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	7	71.00
2	COLLAR SCREW	REPLACE	1.00	\$11.00	7	11.00
	- (REPORTED BY MECHANIC)					
3	COMPARTMENT STORAGE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	CM	210.00
4	COVER DASHBOARD	REPLACE	1.00	\$85.00	(re	85.00
	- (REPORTED BY MECHANIC)					
5	COVER ENGINE (R&G) CASE(RH) KTM ADVENTURE P/N: 50757	REPLACE	1.00	\$232.00	cul	232.00
	- (REPORTED BY MECHANIC)				7	
3	COVER FUEL TANK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,008.00		1,008.00
7	COVER HEADLAMP LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$218.00	CM	218.00
8	COVER HEADLAMP RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$218.00	CM	218.00
9	COVER HEADLAMP UNDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	cn	55.00
0	COVER HEADLIGHT MASK HOLDER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$44.00	mye	88.00
1	COVER HORN FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$67.00	CM	67.00
.2	COVER INNER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	Cre	164.00
3	COVER INNER RH	REPLACE	1.00	\$164.00	Cre	164.00
	- (REPORTED BY MECHANIC)					
4	COVER INTAKE DUCT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	CNZ	85.00
25	COVER INTAKE DUCT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	cro	85.00







Quotation Nos.: 47817

S/N	Description	Action	Qty	Unit Price	<u>Amount</u>
26	COVER INTAKE PORT FOR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	Deg e 55.00
7	COVER INTAKE PORT FOR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	Dept 55.00
8	COVER MUFFLER PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	Cu7 341.00
9	COVER SIDE FRONT UPPER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	CUI 233.00
)	COVER SIDE FRONT UPPER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	(47 233.00
	COVER SPOILER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,024.00	CNC 1,024.00
2	COVER SPOILER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,024.00	One 1,024.00
3	COVERBUSHING CHAIN PROTECTION - (REPORTED BY MECHANIC)	REPLACE	4.00	\$17.00	68.00
	CRASHBAR SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$961.00	Dye 961.00
;	CROWN HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$876.00	34 876.00
6	DAMPER STEERING - (REPORTED BY MECHANIC)	REPLACE	1.00	\$651.00	>7 € 651.00
7	DAMPER STEERING CLAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$202.00	Dyl 202.00
3	EXHAUST MANIFOLD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,410.00	3,410.00
9	EXHAUST PIPE FLANGE GASKET P/N: 63825	REPLACE	2.00	\$55.00	110.00
0	- (REPORTED BY MECHANIC) FOOTREST FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$109.00	C 17 109.00
1	FORK ASSY FRONT SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6,635.00	6,635.00







/N	Description	Action	Qty	Unit Price	1	Amount
2	FORK FRONT SLIDER	REPLACE	1.00	\$141.00	any	141.00
	- (REPORTED BY MECHANIC)					
3	GASKET INTAKE DUCT	REPLACE	2.00	\$28.00		56.00
,	- (REPORTED BY MECHANIC)			68 m (200 m (200 m) (200 m)		
4	HANDGUARD	REPLACE	1.00	\$226.00	cui	226.00
•	- (REPORTED BY MECHANIC)					
5	HANDLEBAR	REPLACE	1.00	\$550.00		550.00
	- (REPORTED BY MECHANIC)					
6	HANDLEBAR RISER	REPLACE	2.00	\$107.00		214.00
J	- (REPORTED BY MECHANIC)					
7	HEADLAMP ADJUSTER	REPLACE	1.00	\$63.00		63.00
•	- (REPORTED BY MECHANIC)					
8	HEADLAMP ADJUSTER THUMBWHEEL	REPLACE	1.00	\$40.00		40.00
	- (REPORTED BY MECHANIC)					
9	HEADLAMP ASSY	REPLACE	1.00	\$3,333.00	Cre	3,333.00
	- (REPORTED BY MECHANIC)					
50	HEADLAMP PROTECTOR	REPLACE	1.00	\$0.00	ner	0.00
	- (REPORTED BY MECHANIC)					
51	HEADLAMP SUPPORT	REPLACE	1.00	\$75.00	sel	75.00
	- (REPORTED BY MECHANIC)					
52	HEADLIGHT MASK	REPLACE	1.00	\$195.00	MI	195.00
	- (REPORTED BY MECHANIC)				1	
53	HEADLIGHT SUPPORT TOP	REPLACE	1.00	\$14.00	?	14.00
	- (REPORTED BY MECHANIC)				·	
54	HH COLLAR SCREW M8X30	REPLACE	2.00	\$11.00	7	22.00
ě	- (REPORTED BY MECHANIC)		- Account to	5.00.000.0000		
55	HORN	REPLACE	1.00	\$122.00	?	122.00
	- (REPORTED BY MECHANIC)					
6	IGNITION KEY PROGRAMMING AT KTM AGENT	REPLACE	1.00	\$745.00	Don a	745.00
.0	- (REPORTED BY MECHANIC)			7)~	







<u> </u>	Description	Action	Qty	Unit Price	Amount
7	LABOUR	Supply/Install	50.00	\$85.00	1900 4,250.00
	P/N: 06766				
	- LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.				
3	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$148.00	LU7 148.00
	- (REPORTED BY MECHANIC)				
9	LOCKSET RACE-ON	REPLACE	1.00	\$2,635.00	2,635.00
	- (REPORTED BY MECHANIC)				
)	MANIFOLD GASKET	REPLACE	1.00	\$55.00	55.00
	P/N: 63849 - (REPORTED BY MECHANIC)				
1	MANIFOLD GASKET 60MM	REPLACE	1.00	\$63.00	63.00
	P/N: 63852				
	- (REPORTED BY MECHANIC)				
2	MASTER CYLINDER PUMP BRAKE RH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,109.00	1,109.00
3	METER ASSY	REPLACE	1.00	\$6,665.00	6,665.00
	- (REPORTED BY MECHANIC)				
1	MIRROR SET	REPLACE	2.00	\$256.00	3NO 512.00
	- (REPORTED BY MECHANIC)				
5	MUDGUARD FRONT	REPLACE	1.00	\$296.00	Cu) 296.00
	- (REPORTED BY MECHANIC)				X
6	MUFFLER (LEOVINCE)	REPLACE	1.00	\$2,140.00	2,140.00
	- (REPORTED BY MECHANIC)				
7	MUFFLER PROTECTOR	REPLACE	1.00	\$71.00	CM7 71.00
	- (REPORTED BY MECHANIC)				
3	NUT SPRING M5	REPLACE	3.00	\$11.00	Men 33.00
	- (REPORTED BY MECHANIC)				
9	OBU TYPE B (12V) NEW	REPLACE	1.00	\$341.00	7 341.00
	P/N: 82490 - (REPORTED BY MECHANIC)				
)	O-RING VITON	REPLACE	1.00	\$17.00	7 17.00
	P/N: 55505 - (REPORTED BY MECHANIC)				. /
1	PEDAL BRAKE	REPLACE	1.00	\$326.00	Ref Cu 326.00
	- (REPORTED BY MECHANIC)	ILI LAOL	1.00	ψ320.00	320.00







Quotation Nos.: 47817

Quota	allon Nos 47017				(,3-	
<u>S/N</u> 72	Description PLATE DISC BRAKE FRONT D=320X4.5 - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	<u>Unit Price</u> \$683.00	? <u>,</u>	683.00
73	POWER SOCKET COMPLETE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	ner	132.00
74	RIM FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,170.00	sol 2	2,170,00
75	SCREW M5X12 - (REPORTED BY MECHANIC)	REPLACE	11.00	\$11.00	ner	121.00
76	SCREW M5X17 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	ser	11.00
77	SCREW M6X18 8.8 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$13.00	ren	52.00
78	STAND MAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$869.00	(u)	869.00
79	STEERING CONE SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00		210.00
80	STICKER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	ner	71.00
81	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$30.00	ner	30.00
82	- (REPORTED BY MECHANIC) STICKER SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$590.00	ner	590.00
83	SWING ARM SLIDER MOTOVATION - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	my	233.00
84	SWINGARM ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4,185.00	(47	4,185.00
85	SWINGARM KIT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$249.00	nu	249.00
86	SWITCH HANDLE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,395.00	11	1,395.00







S/N	<u>Description</u>	Action	Qty	Unit Price		Amount
87	TYRE PRESSURE SENSOR P/N: 81401	REPLACE	1.00	\$427.00	7	427.00
88	- (REPORTED BY MECHANIC) VALVE RIM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	?	91.00
89	WASHER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	7	10.00
90	WASHER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	?	10.00
91	WASHER THRUST 25X35X0.5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	?	5.00
92	WINDSHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	one	388.00
93	WIRE HARNESS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,790.00	?	2,790.00
		SUB TOTAL GST @ 9 %				61,690.00 65,552.10
		GRAND TOTAL (SG	D)		\$6	7,242.10

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray psinting
- To display demand partial disting required
- · Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





